

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

District I

P.O. Box 1980, Hobbs, NM 88240

District II

P.O. Drawer DD, Artesia, NM 88210

District III

1000 Rio Brazos Rd. Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 - 025 - 10683

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
OXY USA INC.

3. Address of Operator  
P.O. Box 50250 Midland, TX 79710

4. Well Location  
Unit Letter E 1,980 Feet From The NORTH Line and 760 Feet From The WEST Line  
Section 9 Township 23 S Range 37 E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3,319

7. Lease Name or Unit agreement Name

SKELLY PENROSE B UNIT

8. Well No. 51

9. Pool name or Wildcat  
LANGLIE MATTIX 7 RVR Q-GB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD - 3630' PERFS - 3480' - 3623'

MIRU PU 4/22/93, POOH W/ RODS & PUMP, NDWH, NUBOP, POOH W/ JUNK TBG. DIG OUT CELLAR, RUN VERTILOG FROM 3415' TO SURFACE. RIH W/ RBP & RTTS & SET @ 3400', ISOLATE CSG LEAK. POOH & SET RBP @ 60' REPLACE 9'- 8-5/8" CSG & 4'- 5-1/2" CSG @ SURFACE. ISOL CSG LK @ 2365'-2334' RIH & TRY TO SET RBP & RTTS PKR, W/O SUCCESS. RIH & SET CIBP @ 3412' & SET 5SX (50') CMT ON TOP. POOH TO 2523' & SET 15 SX (150') PLUG FROM 2523'-2373'. POOH & SHOT 2 SQZ HOLES @ 400', RIH & SET CMT RET @ 349', MIX & PUMP 245SX CL C NEAT, CIRC CMT TO SURFACE & DUMP 15' CMT ON TOP OF RET. POOH TO 60' & SET SURFACE PLUG. REM WH, INSTALL DRY HOLE MARKER, RDPU. NMOCD REP CHARLIE PERRIN WITNESSED, WELL P&A'D 4/29/93.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



TITLE Production Accountant

DATE 05 17 93


TYPE OR PRINT NAME

David Stewart

TELEPHONE NO. 915 685-5717

(This space for State Use)

APPROVED BY



TITLE

OIL & GAS DIVISION

JUL 01 1993

CONDITIONS OF APPROVAL, IF ANY: