

NEW MEXICO OIL CONSERVATION COMMISSION

5-NMCC-HOBBS 1-BH, FIELD CLK
1-R. J. STARRAK-TULSA 1-FILE
1-A. B. CARY-MIDLAND
1-PJB, ENGR.

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR NOTICES TO OIL OR GAS PRODUCERS TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO PRODUCE OIL OR GAS FROM A DIFFERENT RESERVOIR")

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER - Injection
2. Name of Operator
Getty Oil Company
3. Address of Operator
P. O. Box 730, Hobbs, NM 88240
4. Location of Well
UNIT LETTER D 660 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE, SECTION 10 TOWNSHIP 23-S RANGE 37-E NMPL.

7. Unit Agreement Name
Skelly Penrose A Unit
8. Form of Lease Name

9. Well No.
44
10. Field and Pool, or Wildcat
Langlie Mattix

15. Elevation (Show whether DF, KT, GR, etc.)
3300 D.F.

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐ CHANGE PLANS ☐ CASING TEST AND CEMENT JOB ☐
OTHER ☐ OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit. Install BOP.
2. Pull tbgs. and pkr.
3. Set BP at 3250'.
4. Run cement bond log and locate cement top.
5. Perforate and squeeze cement. Attempt to circulate to surface.
6. Retrieve BP.
7. Clean out well to TD.
8. Acidize perms. 3516-3618 with 1500 gals. 15% NE acid.
9. Return well to injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dale R. Crockett TITLE Area Superintendent DATE 11-9-79

APPROVED BY Jerry Sexton TITLE Dist 1. Supv. DATE NOV 15 1979
CONDITIONS OF APPROVAL, IF ANY