

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

LC 030186A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

CLINE A-15 #1

9. API Well No.

30-025-10718

10. Field and Pool, or Exploratory Area

LANGLIE-MATTIX 7 RVRS Q

11. County or Parish, State

LEA, NM

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil ☐ Gas ☐ Other
☒ Dry Well ☐ Well ☐ Other

2. Name of Operator

Conoco Inc.

3. Address and Telephone No.

10 Desta Drive STE 100W, Midland, TX 79705 (915)686-5424

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FNL & 1980' FWL, SEC. 15, T-23S, R-37E, UNIT LTR 'C'

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☒ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completions on Well Completion or Perforation Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

5-28-91 MIRU, DIG OUT WELLHEAD. RIH W. SCRAPER TO 3270' POOH.
(BLM OK NOT TO RUN CNT RET) RIH W/ TBG TAG @ 3615', CIRC MUD TO SURFACE, PUMP 100SX CMT
FROM 3600-3000'. RIH TAG CMT 3377', PUMP 100SX CMT WAIT 4 HRS.
RIH TAG CMT 3360', PUMP 100 SX CMT PUH TO 2000'.
RIH TAG CMT @ 2785'. PUH SPOT 25 SX CMT 2575-2425' POOH.
PERF @ 1240', CIRC MUD, RIH TO 1300' SPOT 40 SX CMT FROM 1300-1100 INSIDE & OUT OF 7" &
8 5/8" POOH. RIH TAG @ 1100'.
PERF @ 400', CIRC MUD DOWN 7" & OUT 16" - PUMP 245 SX CMT TO SURFACE ON 16" & DOWN TO 350'
PERF @ 270', CIRC MUD DOWN 7" OUT 8 5/8" - PUMP 70 SX CMT TO FILL
7" & 8 5/8" TO SURFACE. CUT OFF WELLHEAD.
RDMO
INSTALL P&A MARKER.
THIS WELL P&A ON 6-3-91.

Approved as to plugging of this well bore.
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed _____ Title SR. REGULATORY SPEC. Date 6-30-92

(This space for Federal or State office use)

Approved by _____ Title _____ Date 7/8/92
Conditions of approval, if any:

RECEIVED

JUL 09 1992

OCD HOBBS OFF