Form 3160-5 (June 1990)	t، ED STA DEPARTMENT OF THE	TES	N.M. Oil	500440000	-
June 1990)	DEPARTMENT OF THE		IN.IVI. 1911	FORM APPROVE	
			P.O. Box 198	Budget Bureau No. 100	4-0135
	BUREAU OF LAND MAI	NAGEMENT		Expires: March 31, 1 5. Lease Designation and	
			Hobbs, NM .	LC 03l086A	
	SUNDRY NOTICES AND REP	ORTS ON WELL	S	6. If Indian, Atlottee or Trib	e Name
Do not use this form for proposi	als to drill or to deepen or ree	ntry to a different	reservoir.		
Use "APPLICATION F	FOR PERMIT - " for such propo	usals		1 Hindor () A Annual State	t Depender
	SUBMIT IN TRIPLIC	ATE		7. If Unit or CA, Agreemen	Lesignauon
Type of Well				-	
X Oil Gas IN Well Well Other	IJECTION				
Name of Operator	,	<u> </u>		8.VINAME OF JEASE & WEIL Cline A-15	
CONOCO, INC.				Well #3 9. 7api well #	
Address and Telephone No.				30 025 10734	
10 Desta Dr., Suite IOOW, Midlar Location of Well (Footage, Sec., T., R., M	nd, Texas 79705-4500,915 686-54	<b>24 915 684-63</b> 81		10. Field and Pool, or Exp	loratory Area
				Langlie Mattix 7 Rv	
Surface: 1980' FSL & 660' fWL Sec 15, T23S, R37E, Unit Ltr L TD: same as above				11. County or Parish, State	9
				Lea, NI	M
	E BOX(s) TO INDICATE NA	TURE OF NOT	ICE. REPORT OP		
			TYPE OF ACTION		
Notice of Intent		Abandonr		Change of Plans	
X Subsequent Report		Plugging		New Construction	a
		Casing R		Water Shut-Off	Я
Final Abandonment No	otice	Altering C		Conversion to Injection	l
		X tubing/rods		Dispose Water	
				Note: Report results of multiple comp	plation on Well
12-21-98: MIRU, fish po NU BOP, scano	olish rod, work pump, free P blog SION	OOH w/rods &	pump, all rods pitted	l, ND weilhead,	
NU BOP, scano 12-22-98: Open up well couldn't get dow 12-17-98: RIH w/produc	blish rod, work pump, free P blog. SION. finish laying down tbg, rack vn, POOH - SN bad, SION. ction tubing, ND BOP, NU w hung well on, loaded hole, d	c & taily tbg, Rif eliehad, RiH w/	H w/SN, tagged @ 3	412', worked w/tbg,	
NU BOP, scano 12-22-98: Open up well couldn't get dow 12-17-98: RIH w/produc picked up rods,	olog. SION.   finish laying down tbg, rack vn, POOH - SN bad, SION. ction tub <del>i</del> ng, ND BOP, NU <del>w</del>	k & tally tbg, RIH rellehad, RIH w/ checked pump	H w/SN, tagged @ 3	412', worked w/tbg,	
NU BOP, scano 12-22-98: Open up well couldn't get dow 12-17-98: RIH w/produc picked up rods,	blog. SION. finish laying down tbg, rack vn, POOH - SN bad, SION. ction tubing, ND BOP, NU w hung well on, loaded hole, o	k & tally tbg, RIH rellehad, RIH w/ checked pump	H w/SN, tagged @ 3	412', worked w/tbg,	
NU BOP, scano 12-22-98: Open up well couldn't get dow 12-17-98: RIH w/produc picked up rods,	blog. SION. finish laying down tbg, rack vn, POOH - SN bad, SION. ction tubing, ND BOP, NU w hung well on, loaded hole, o	k & tally tbg, RIH rellehad, RIH w/ checked pump	H w/SN, tagged @ 3 rods, POOH & layed action, left well on.	412', worked w/tbg, I down rods, RIH w/	/pump,
NU BOP, scano 12-22-98: Open up well couldn't get dow 12-17-98: RIH w/produc picked up rods,	blog. SION. finish laying down tbg, rack vn, POOH - SN bad, SION. ction tubing, ND BOP, NU w hung well on, loaded hole, o	k & tally tbg, RIH rellehad, RIH w/ checked pump	H w/SN, tagged @ 3 rods, POOH & tayed action, left well on.	412', worked w/tbg, I down rods, RIH w/	/pump,
NU BOP, scano 12-22-98: Open up well couldn't get dow 12-17-98: RIH w/produc picked up rods,	blog. SION. finish laying down tbg, rack vn, POOH - SN bad, SION. ction tubing, ND BOP, NU w hung well on, loaded hole, o	k & tally tbg, RIH rellehad, RIH w/ checked pump	H w/SN, tagged @ 3 rods, POOH & tayed action, left well on.	412', worked w/tbg,	/pump,
NU BOP, scano 12-22-98: Open up well couldn't get dow 12-17-98: RIH w/produc picked up rods,	blog. SION. finish laying down tbg, rack vn, POOH - SN bad, SION. ction tubing, ND BOP, NU w hung well on, loaded hole, o	k & tally tbg, RIH rellehad, RIH w/ checked pump	H w/SN, tagged @ 3 rods, POOH & tayed action, left well on.	412', worked w/tbg, I down rods, RIH w/	/pump,
NU BOP, scano 12-22-98: Open up well couldn't get dow 12-17-98: RIH w/produc picked up rods,	blog. SION. finish laying down tbg, rack vn, POOH - SN bad, SION. ction tubing, ND BOP, NU w hung well on, loaded hole, o	k & tally tbg, RIH rellehad, RIH w/ checked pump	H w/SN, tagged @ 3 rods, POOH & tayed action, left well on.	412', worked w/tbg, I down rods, RIH w/ DAVID R. GLASS	/pump,
NU BOP, scano 12-22-98: Open up well couldn't get dow 12-17-98: RIH w/produc picked up rods, Pulled 3608' 2 3	olog. SION. finish laying down tbg, rack vn, POOH - SN bad, SION. ction tubing, ND BOP, NU w hung well on, loaded hole, o 3/8" tubing, ran 3354' 2 3/8"	k & tally tbg, RIH rellehad, RIH w/ checked pump	H w/SN, tagged @ 3 rods, POOH & layed action, left well on.	412', worked w/tbg, I down rods, RIH w/ DAVID R. GLASS	/pump,
NU BOP, scano 12-22-98: Open up well couldn't get dow 12-17-98: RIH w/produc picked up rods, Pulled 3608' 2 3	olog. SION. finish laying down tbg, rack vn, POOH - SN bad, SION. ction tubing, ND BOP, NU w hung well on, loaded hole, 3/8" tubing, ran 3354' 2 3/8"	c & tally tbg, RIH reliehad, RIH w/ checked pump tubing.	H w/SN, tagged @ 3 rods, POOH & layed action, left well on.	412', worked w/tbg, I down rods, RIH w/ DAVID R. GLASS	/pump,
NU BOP, scano 12-22-98: Open up well couldn't get dow 12-17-98: RIH w/produc picked up rods, Pulled 3608' 2 3	blog. SION. finish laying down tbg, rack wn, POOH - SN bad, SION. ction tubing, ND BOP, NU w hung well on, loaded hole, o B/8" tubing, ran 3354' 2 3/8"	c & tally tbg, RIH reliehad, RIH w/ checked pump tubing.	H w/SN, tagged @ 3 rods, POOH & layed action, left well on.	412', worked w/tbg, I down rods, RIH w/ DAVID R. GLASS	/pump,
NU BOP, scano 12-22-98: Open up well couldn't get dow 12-17-98: RIH w/produc picked up rods, Pulled 3608' 2 3	Ann E. Rite Title	c & tally tbg, RIH rellehad, RIH w/ checked pump tubing.	H w/SN, tagged @ 3 rods, POOH & layed action, left well on.	412', worked w/tbg, I down rods, RIH w/ DAVID R. GLASS	/pump,
NU BOP, scano 12-22-98: Open up well couldn't get dow 12-17-98: RIH w/produc picked up rods, Pulled 3608' 2 3 Thereby certify that the foregoing is frue & Signed (This spece for Federal or State office use pproved by	Ann E. Rite Title	c & tally tbg, RIH rellehad, RIH w/ checked pump tubing.	H w/SN, tagged @ 3 rods, POOH & layed action, left well on.	412', worked w/tbg, I down rods, RIH w/ DAVID R. GLASS	/pump,
NU BOP, scano 12-22-98: Open up well couldn't get dow 12-17-98: RIH w/produc picked up rods, Pulled 3608' 2 3 Pulled 3608' 2 3 Thereby certify that the foregoing infrue 4 Signed (This space for Federal or State office use opproved by Conditions of approval, if any e 18 U.S.C. Section 1001, makes it a crime	e for any person knowingly and wilffully to r	c & tally tbg, RIH reliehad, RIH w/ checked pump tubing.	H w/SN, tagged @ 3 rods, POOH & tayed action, left well on.	412', worked w/tbg, I down rods, RIH w/ DAVID R. GLASS	/pump,
NU BOP, scano 12-22-98: Open up well couldn't get dow 12-17-98: RIH w/produc picked up rods, Pulled 3608' 2 3 Thereby certify that the foregoing is frue & Signed (This space for Federal or State office use pproved by	e for any person knowingly and wilffully to r	c & tally tbg, RIH reliehad, RIH w/ checked pump tubing.	H w/SN, tagged @ 3 rods, POOH & tayed action, left well on.	412', worked w/tbg, I down rods, RIH w/ DAVID R. GLASS	/pump,

 $\mathcal{S}$