

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 2244

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hughes Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Langlie Mattix (7R-Q-GB)

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

17-23S-37E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER WIW

2. NAME OF OPERATOR

Samedan Oil Corporation

3. ADDRESS OF OPERATOR

10 Desta Drive, Suite 240 East, Midland, Texas 79705

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

660' FEL &amp; 660' FSL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3335'K

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

3-4-87 Install BOP. Released and pulled Baker AD-1 Pkr out of hole.  
POH w/112 Jts 2 3/8" PCID Tbg (3436.33).3-5-87 TIH with 2 3/8" Tbg. Tag up on CIBP @ 3692'. POH. TIH w/4 1/2" CIBP & set @ 3418'.  
Spot 35' of Cmt on Top of CIBP.3-6-87 McCullough perfed 4 1/2" Csg @ 1164' from surface w/4 holes. Inj water @ rate of  
3 1/2 bbls/min. No PSI. Cire hole. Pump 86 sx. Plug displaced cmt to 1014' from  
surface. BLM man on location.3-7-88<sup>87</sup> Pressure up on plug @ 1015' F/15". Held O.K. McCullough shot 4 squeeze holes @  
189' from surface. Established inj water & pumped 55 sx cmt down 4 1/2" csg. Displaced  
to 10' below ground level. Cut into 7" csg 4' below ground level found cmt. Cut  
off 4 1/2 csg. Install dry hole marker. BLM man on location - Said O.K.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Div. Production Clerk

DATE 2/5/88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

SJS

RECEIVED

RECEIVED  
MAR 11 1968  
FBI - NEW YORK