

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Sinclair Oil &amp; Gas Company</b>	8. Farm or Lease Name <b>Duthie-Andrews Unit WN</b>
3. Address of Operator <b>P. O. Box 1920, Hobbs, New Mexico, 88240</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>J</b> , <b>1980</b> FEET FROM THE <b>S</b> LINE AND <b>1980</b> FEET FROM THE <b>E</b> LINE, SECTION <b>18</b> TOWNSHIP <b>23S</b> RANGE <b>37E</b> NMPM.	10. Field and Pool, or Wildcat <b>Jalnat (Yates)</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3344' DF</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> <b>Squeeze Cement, perf, Acidize, frac&amp;test.</b>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1-20-65 Ran Gamma/Neutron and Bond log 2650' to TD.
- 1-21-65 Set CI bridge plug 3308'. Jet perf. 7"OD 24# esg @ 3174'-3176' w/ 4-3/8" holes. Set C.I. retainer @ 3134', squeezed perfs. w/100 sks. Inscr neat wt. 14.8# preceded by 250 gals. M.A. Max. Press. 2000#.
- 1-22-65 Ran temperature log after 1st squeeze, indicated no change from bond log. Jet perf. 7"OD esg. 2670-72' w/4 - 3/8" holes. Set C.I. retainer @ 2630', squeezed thru perforations 2670-72' w/100 sks. Inscr cement 14.9# preceded by 250 gal. M.A. reverse out 5 sks. No circulation. WOO 24 hrs.
- 1-24-65 Drill C.I. retainer @ 2630'. Good cement to 2675'. Test squeeze perfs. 2670-72' to 1500# for 30 minutes. Tested O.K. Washed to 3134' PHD.
- 1-26-65 Jet perf. Jalnat (Yates) 2688-90', 2782-84', 2812-16', 2841-43', 2932-35', 3043-46', 3059-61', 3068-70', 3092-94', 3106-08' w/48 - 3/8" holes.
- 1-27-65 Ram tubing and packer to 2650' and mud acid wash Jalnat (Yates) perfs. 2688-3108' w/2000 gal. M.A. and additives Max. Press. 2600#, Min. 1000# @ 5.3 BPM. Inst. SIP 1800# in 10 min. SIP 200#.
- 1-29-65 Sand oil frac perfs. 2688-3108' w/20000 gal. refined oil and 20000# sand, 35 gal. Sinclair BIA Compound, and 40 ball sealers, Max. Press. 4500#, Min. 4000# @ 13 BPM. Inst. SIP 1800#, 10 min. SIP 1450#.
- 2-2-65 Flowed Jalnat perfs 2688-3108' gas @ rate of 2,180MCF for 10 hrs. on 20/64" choke. Tbg Press. 500#.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Press. 500#.

SIGNED Jack R. ... TITLE **Area Superintendent** DATE **2-3-65**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

Orig 3cc: CCC, Hobbs, cc: Mr. R.F. Sawyer, cc: file

1. *Chlorophyll a* and *Chlorophyll b* were determined by the method of Lichtenthaler and Whistler (1973).

[illegible]

1. What is the purpose of the study?

2013年12月15日 星期一 晴