

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSIX COPIES
SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different rock zone.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
SAMEDAN OIL CORPORATION	Hughes "B"
3. ADDRESS OF OPERATOR	9. WELL NO.
600 N. Marienfeld, Suite 320 - Midland, TX 79701	G-1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT
990' N & 1650' W	Jalmat Yates
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH
3346' DF	13. STATE
	19-23S-37E
	LEA New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input checked="" type="checkbox"/>
(Other)	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

P&A. Run 5 1/2" cast iron bridge plug on tubing and set @ 2702'. Displace hole with gel laden fluid - spot 10 sacks Class "C" cement from 2702' to 2650' - pulled 65 jts of tubing and spot 30 sacks Class "C" cement plug from 850' to 750' - pulled remainder of tubing. Removed BOP and ran 3 jts of tubing and pumped 10 sacks Class "C" cement plug from 90' to surface. Circulated 4 sacks to pit. Set dry hole marker. Cut off pulling unit anchor and clean up location. Location is ready for inspection.

RECEIVED
FEB 11 1982OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWell, NEW MEXICO

Oral agreement made with Ross Robinson, surface land owner, to cleanup location after completion of plugging operations to his satisfaction.

18. I hereby certify that the foregoing is true and correct

SIGNED Arthur Diamond TITLE DIVISION CLERK DATE 2-9-82

(This space for Federal or State Approval)

APPROVED BY James A. Gillham TITLE DISTRICT SUPERVISOR DATE NOV 2 1982

CONDITIONS OF APPROVAL, IF ANY:

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side

RECEIVED
NOV 5 1982
C. D.
HOBBS OFFICE