

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|   |   |
|---|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Injection</u> <u>Lead</u>  | 7. Unit Agreement Name                                  |
| 2. Name of Operator<br><u>Millard Deck Estate</u>   | 8. Farm or Lease Name<br><u>Steeler SWD</u>             |
| 3. Address of Operator<br><u>Box 871 Kermit, TX. 79745</u>  | 9. Well No.<br><u>1</u>                                 |
| 4. Location of Well<br>UNIT LETTER <u>L</u> <u>1980'</u> FEET FROM THE <u>South</u> LINE AND <u>660'</u> FEET FROM<br>THE <u>East</u> LINE, SECTION <u>20</u> TOWNSHIP <u>23</u> RANGE <u>37</u> N.M.P.M. | 10. Field and Pool, or Wildcat<br><u>Langley Mattix</u> |
| 15. Elevation (Show whether DF, RT, GR, etc.)   | 12. County<br><u>Lea</u>                                |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

|  |  |
|--|--|
| NOTICE OF INTENTION TO:                        | SUBSEQUENT REPORT OF:                                    |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>                   |
| TEMPORARILY ABANDON <input type="checkbox"/>   | COMMENCE DRILLING OPNS. <input type="checkbox"/>         |
| PULL OR ALTER CASING <input type="checkbox"/>  | CASING TEST AND CEMENT JOB <input type="checkbox"/>      |
| OTHER <input type="checkbox"/>                 | OTHER <input type="checkbox"/>                           |
| PLUG AND ABANDON <input type="checkbox"/>      | ALTERING CASING <input checked="" type="checkbox"/>      |
| CHANGE PLANS <input type="checkbox"/>          | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Cut tubing @ 3100' and spot 25 sacks of cement.
2. Load hole with mud.
3. Perforate @ 300'.
4. Run 5 joints of tubing and well head. Squeeze 80 sacks of cement.
5. Tag plug @ 225'.
6. Cut well head and set 15' surface plug.
7. Install P & A marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Raymond M. Debnado TITLE Baber Well Service P.O. Box 1772 Hobbs, NM 882  
P & A Supervisor DATE 9-23-86

APPROVED BY Eel McRe TITLE Petroleum Engineer DATE 10-14-86

CONDITIONS OF APPROVAL, IF ANY:

2-25-03