OIL CONSERVATION COMMISSION

HOBBS. NEW MEXICO

Oct. 28, 1957

Resler & Sheldon 302 Carper Bldg. Artesia, New Mex.

Dear Mr. Sheldon:

It will be necessary that a 20 sack plug be placed in and out the base of the 9.5/8" casing.

If left as is gas might enter the hole and accumulate below surface plug. If someone should reenter the well later on, mud pressure may be insufficient to contain this gas and the well could blow out with injurious results. A possibly serious accident may be prevented by placing a plug in the base of the 9 $5/8^{\circ}$.

Please notify this office when subject plug has been placed.

Yours very truly,

OIL CONSERVATION COMMISSION

E. J. Fischer Engineer, District 1

EJF/mc

cc-OCC, Santa Fe

R. F. Montgomery OCC, Hobbs

June 103