

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION, C. C.

JAN 19 3 24 PM '66

Form C-100
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation		8. Farm or Lease Name E. C. Hill (Tr. A)
3. Address of Operator P. O. Box 980, Kermit, Texas		9. Well No. 1
4. Location of Well UNIT CENTER K 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 27 TOWNSHIP 23-S RANGE 37-E NMPM.		10. Field and Pool, or Wildcat Iangle Mattix
15. Elevation (Show whether DF, RT, GR, etc.) 3292 GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in casing pullers and spotted 25 sx cmt @ 3557', W0 cmt, check plug, O.K. Mudded up hole. Shot 7" casing @ 3175', could not pull, shot @ 3023' and pulled 92 jts 7" casing. Ran tubing and spotted two 25 sx cmt plugs @ 3020' & 2900'. Shot 9-5/8" casing @ 1800'; 1500'; & 1000', could not pull. Shot @ 500' and recovered 16 jts 9-5/8" casing. Spotted two 25 sx cmt plugs @ 500' & 300' and from 50' to surface. Set marker. Left 6750' of 7" casing, 2388' of 9-5/8" casing and 288' of 13-3/8" casing in the hole. Location is cleaned up and ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. W. Whitaker TITLE Area Engineer DATE January 18, 1966

APPROVED BY Leslie A. Clements TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: