Form 9-331 (May 1963)					
		UNI D STATES SUBMIT IN TRIPL EPARTMENT OF THE INTERIOR verse side)		Form approved.     Budget Bureau No. 42-R1424	
				5. LEASE DESIGNA	TION AND SERIAL NO.
		GEOLOGICAL SURVEY		LC-030187	
		FICES AND REPORTS sals to drill or to deepen or plug ATION FOR PERMIT—" for such		6. IF INDIAN, ALLA	OTTEE OR TRIBE NAME
1.				7. UNIT AGREEMEN	T NAME
OIL GAS WELL WELL	OTHER	Water Injecti	on Holl		
2. NAME OF OPERATOR	8. FARM OR LEASE	NAME			
Cult Oil Cor	C E LoMunyon				
Gulf Oil Cor 3. Address of Operat	OR	9. WELL NO.	C. E. LaMunyon 9. Well NO.		
Port 670 Uch	ha Nor Ma	9			
<ul> <li>Box 670, Hobbs, New Mexico 88240</li> <li>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface</li> <li>O' FNL &amp; 660' FWL, Section 27, 23-S, 37-E</li> </ul>				10. FIELD AND POOL, OR WILDCAT	
				Teague Simpson	
				11. SEC., T., R., M.	11. SEC., T., R., M., OR BLK. AND SURVEY OR ABEA
0 1112 0 000		•••••••••••••••••		SURVEI OR	ARDA
				Sec 27, 23	-S. 37-Е
14. PERMIT NO.		15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	12. COUNTY OR PA	
		329	9' DF	Lea	New Mexi
				<b>_</b>	
			Nature of Notice Report or		
16.	Check A	ppropriate Box To Indicate	a ranne of rance, kepon, or	Other Data	. •
<b>16.</b>	Check A NOTICE OF INTE			QUENT REPORT OF:	1. T 1.
	NOTICE OF INTE			QUENT REPORT OF:	ING WELL
16. TEST WATER SHUT FRACTURE TREAT	NOTICE OF INTE	NTION TO:	SUBSE	QUENT REPORT OF :	ING WELL
TEST WATER SHUT	NOTICE OF INTE	PULL OR ALTER CASING	SUBSE WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING	QUENT REPORT OF: REPAIR ALTERI ABANDO	
TEST WATER SHUT FRACTURE TREAT	NOTICE OF INTE	PULL OR ALTER CASING	SUBSE WATER SHUT-OFF FRACTURE TREATMENT	QUENT REPORT OF: REPAIR ALTERI ABANDO	NG CASING
FRACTURE TREAT Shoot or acidize	NOTICE OF INTE	NTION TO: PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON*	SUBSE WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Repaired CA (NOTE: Report resul	QUENT REPORT OF: REPAIR ALTERI ABANDO	NG CASING

Pulled injection equipment on April 4, 1976. Located leak in 7" casing between 3427' and 4272'. Set retainer at 3342' and squeezed with total of 800 sacks of light cement and 500 sacks of Class C cement containing 5# salt per sack. Pumped 825 sacks and circulated to surface out 9-5/8" casing. Closed 9-5/8" casing valve and squeezed balance of cement (475 sacks) into formation. WOC 41 hours. Ran bit and drilled retainer at 3342' and cement to 4272'. Tested casing with 500#, 30 minutes, OK. Circulated hole clean. Ran 2-3/8" tubing and set in Baker Model D packer at 9221'. Work completed on June 15, 1976.

18. I hereby certify that the foregoing is true and correc SIGNED D. J. Burlin	t <sub>TITLE</sub> Area Engineer	DATE June 15, 1976
(This space for Federal or State office use)	TITLE	JIFTED FOR RECOND
CONDITIONS OF APPROVAL, IF ANY:		JUN 1.8 1976
*.	See Instructions on Reverse Side	J. S. GECLOGICAL SURVEY HOBBS, NEW MEXICO