				<i>C</i> **		
		х /		*		
Form 9-331 (May 1963)	DEPARTI	UNITED STATES MENT OF THE INTI GEOLOGICAL SURVEY			au No. 42-R1424.	
		ICES AND REPORT sals to drill or to deepen or pl ATION FOR PERMIT—" for su	S ON WELLS lug back to a different reservoir. sch proposals.)	6. IF INDIAN, ALLOTTE	E OR TRIBE NAME	
1. OIL GAS WELL WELL	7. UNIT AGREEMENT NAME					
2. NAME OF OPERATOR		8. FARM OR LEASE NAME				
Gulf Oil Cor	poration	C. E. LaMun	C. E. LaMunyon			
3. ADDRESS OF OPERAT		9. WELL NO.				
Box 670, Hob	13	13				
4. LOCATION OF WELL See also space 17 be At surface	Report location c	10. FIELD AND POOL, OR WILDCAT North Teague Devonian				
190	J FNL & L	11. SEC., T., R., M., OR BLK. AND SURVEY OR ABEA Section 27-235-37E				
14. PERMIT NO.		15. ELEVATIONS (Show wheth	AT DE ET CP ata)	12. COUNTY OR PARISE		
14. PERMIT NO.			er br, ki, ok, ew.y			
		3284' GL		Lea	N.M.	
16.	Check A	opropriate Box To Indicat	te Nature of Notice, Report, or	Other Data		
NOTICE OF INTENTION TO:			SUBSE	SUBSEQUENT REPORT OF:		
TEST WATER SHUT	OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING	WELL	
FRACTURE TREAT		MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTEBING C	ASING	
SHOOT OR ACIDIZE		ABANDON*	SHOOTING OR ACIDIZING	ABANDONME		
REPAIR WELL		CHANGE PLANS	(Other) Abandoned			
(Other)			(Note: Report resul Completion or Recom	ts of multiple completion pletion Report and Log fo	on Well orm.)	
17. DESCRIBE PROPOSED proposed work.	OR COMPLETED OPH If well is direction	RATIONS (Clearly state all pertonally drilled, give subsurface	tinent details, and give pertinent date locations and measured and true vert	es, including estimated da ical depths for all marker	te of starting any 's and zones perti-	
nent to this work.	) *		*Nort	th Teague Devoni	lan	

7480' PB. Pulled injection equipment. Set cement retainer at 9100'. Tested casing with 1000#, OK. Spotted 100' cement plug on top of cement retainer, abandoning Teague Simpson perforations 9226 to 9379'. Perforated 7" casing with 4, ½" JHPF at 7655-7665'. Acidized new perforations with 3000 gallons 15% NE acid. Swabbed and tested, no show oil or gas. Set cement retainer at 7620'.Sqzd perfs 7655-65 w/100 sx Cl. C .. Perforated 7" casing with 4, ½"JHPF at 7565' to 7575'. Acidized new perforations with 3100 gallons 15% NEacid. Average pressure 3700#, AIR 4.75 bpm, ISIP 1250#; after 15 minutes 500#. Swabbed and cleaned up, no commercial production. Set cement retainer at 7540' and squeezed perforations 7565' to 7575' with 100 sacks Class C cement; capped cement retainer with 5' cement. Perforated 7" casing with 4, 2" JHPF at 7500-7510'; acidized perforations 7500-7510' with 3100 gallons 15% NEFE acid. Average pressure 3500# . AIR 4.5 bpm. ISIP 1500#, after 15 minutes 1000#. Swabbed and cleaned up. No commercial production. Set CIBP at 7480'. Perforated 7@ casing with 4, 2" JHPF at 7438-7450'. Acidized new perforations 7438-7450' with 3100 gallons 15% NEFE acid. Average pressure 3500#, AIR 4.8 bpm. ISIP 1600#; after 15 minutes 1050#. Swabbed and cleaned up. Tested well from North Teague Devonian zone. Well is closed in waiting on pipeline connection. Work performed May 23 to June 16, 1977.

įr

18. I hereby certify that the foregoing is true and correct SIGNED	TITLE Area Engineer	DATE 8-5-77
(This space for Federal or State office use)		AUGEFTED TON NEODND
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	AUGATE 1977
*		U. S. GEOLOGICAL SURVEY
*Se	e Instructions on Reverse Side	HOBBS, NEW MEXICO

 $\mathcal{D}_{i}$