

Form 9-311
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on reverse)
RECEIVED

Form approved
Budget Bureau No. 42-11121
LEASE DESIGNATION AND SERIAL NO.

LC-030187

IF INDIAN, ALLOTTEE OR TRIBE NAME

UNIT AGREEMENT NAME

NAME OF LEASEE

C.E. LaMunyon

WELL NO.

170X

FIELD AND TOWN, OR WILDCAT

SEC. T. R. M. OR R.R. AND SURVEY OR AREA

Sec 28-T23S-R37E

COUNTY OR PARISH

Lea

STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ *Lt Disposal*

2. NAME OF OPERATOR
Gulf Oil Corporation

3. ADDRESS OF OPERATOR
P. O. Box 670, Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

766' FNL + 554' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, BT, CA, etc.)

3294' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

POH w/ thg. Set CIBP @ 4099'. Circ hole w/ brine w/ gel. Spot 35' cmt on CIBP. Spot plug @ 6050-6150' + 3150-3250'. Set CIBP @ 2679'. Wp w/ 35' cmt. Perf 1099-1101' w/ 4" 1/2" JHPF. Establish injec rate @ 3 1/2 BPM, 1000#. Set cmt ret. @ 1000'. Log perfor 1099-1101' w/ 400 sq ft "C" mat @ 1000#, obtained sq of 1250#. Dump 30' cmt on cmt ret. Run temp surv, top of cmt @ 570'. RHA to 60' w/ thg. Load hole w/ 10# salt gel. Spot surf plug. POH w/ thg. Install dry hole marker. P+A 1-4-84.

18. I hereby certify that the foregoing is true and correct

SIGNED *R.D. Pitre*

TITLE Area Engineer

DATE 1-17-84

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE