		COPY TO	in (1. 4 <b>.</b>	L		
Form 9-331 (May 1963)	DEPART	UNIICD STATI		SUBMIT IN TRIPLICA (Other instructions on verse side)		Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.
	GEOLOGICAL SU				LC-030187	
				·	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
(Do not use this	form for prop Use "APPLIC	Station For PERMIT	en or plug back	to a different reservoir. sals.)		
1. OIL GAS WELL WELL	Water Disposal	.Well			7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR				5 3 6 10 10		S. FARM OR LEASE NAME
GULF OIL CO	RPORATION	1		10 - 191	<u>y</u>	C. E. LaMunyon
3. ADDRESS OF OPERATO	8			001 et al 1	SUP	9 VELL NO.
P.O. Box 67	0, Hobbs,	, NM 88240		OGICAL	-CXI	<u>0 6</u>
4. LOCATION OF WELL ( See also space 17 be) At surface	Report location low.)	clearly and in accordance	ce with any Sta	te requirementation (CGiCAL U. S. NEW N HOBBS, NEW N	WILL CO	10. FIELD AND POOL, OR WILDCAT Teague Simpson
766' FNL &	554' FEL			n <sup>3</sup>	ľ	11. SEC., T., B., M., OR BLK. AND- SURVEY OR AREA
						Unit A
	-,, ·					Sec 28-T23S-R37E
14. PERMIT NO.		15. ELEVATIONS (Show	w whether DF, RT,	GR, etc.)		12. COUNTY OR PARISH 13. STATE
			328	32' GL	ŀ	Lea NM
16.					~ 0	abor Dota
10.	Check A	Appropriate box to t	nalcare inati	ure of Notice, Report,		
	NOTICE OF INTE	INTION TO:		SUI	BSEQUE	INT REPORT OF:
TEST WATER SHUT-	FF	PULL OR ALTER CASING		WATEB SHUT-OFF		REPAIRING WELL
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT		ALTERING CASING
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING	X	ABANDONMENT*
REPAIR WELL		CHANGE PLANS		(Other)		
(Other)				Completion or Rec	comple	of multiple completion on Well tion Report and Log form.)
17. DESCRIBE PROPOSED 0 proposed work. I nent to this work.)	f well is direct	PERATIONS (Clearly state tionally drilled, give subs	all pertinent de surface location:	etails, and give pertinent d s and measured and true v	lates, i ertical	including estimated date of starting any depths for all markers and zones perti-
HC1 acid as Increased r to 2900#.	follows: ate to 1½ Incr rate	Ppd 1320 gal BPM & pres in	s acid @ acr to 300 pres incr	1 BPM @ 3000#, H 00#. Ppd 1680 ga to 3000#. Flush	orok als	00 gals NE inhibited e back to 2850#. acid. Broke back w/50 bbls 8.6# Gulf
5 <b>7</b> 9 BW inje	cted in 2	24 hrs. 425 BW	injected	l before acid jol	b.	
Work perfor	med 10-19	9-79 through 10	-21-79.			
						•
		,				
						<u> </u>

.

18. I hereby certify that the foregoing is true and correct SIGNED	TITLE	Area Engineer FOR RECORD DATE 10-23-79
(This space for Federal or State office use)		ACCEPTED 10 6 1979
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	OCT-20 OCT-20 U. S. GEOLOGICAL SUTTING U. S. GEOLOGICAL SUTTING U. S. GEOLOGICAL SUTTING MEXICO Ons on Reverse Side HOBBS, NEW MEXICO
*Se	e Instructi	ons on Reverse Side HOBBS: