

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator <b>ALBERT GACKLE, OPERATOR</b>		8. Farm or Lease Name <b>R. W. Cowden</b>
3. Address of Operator <b>BOX 2038, HOBBS, N. M. 88240</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>J</b> <b>1650'</b> FEET FROM THE <b>South</b> LINE AND <b>1650'</b> FEET FROM THE <b>East</b> LINE, SECTION <b>30</b> TOWNSHIP <b>23S</b> RANGE <b>37E</b> NMPM.		10. Field and Pool, or Wildcat <b>Jalmat</b>
15. Elevation (Show whether DF, RT, GR, etc.)		12. County <b>Lea</b>

16.

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**This well has 2-7/8" tubing which is plugged.**

**We propose to kill well; pull 2-7/8" tubing; clean well out to bottom; replace 2-7/8" tubing with 2-3/8" tubing. Put well back to producing.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Albert Gackle* TITLE Operator DATE 10-15-1970

APPROVED BY *J. R. [Signature]* TITLE SECRETARY DATE 10-15-1970

CONDITIONS OF APPROVAL, IF ANY: