OFFICE OR SUNDE	NEW ME	XICO OIL CONSERVATE		Supersedes Old
OR SLINDS	- NEW ME	XICO OIL CONSERVATE	5-3-3-3-3-3-3-3-3-3-4-4-4-4-4-4-4-4-4-4-	C-102 and C-103
OR SLINDS			NE COMMISSION	Effective 1-1-65
OR SUNDI				Sa. Indicate Type of Lease
SUND				State Fee K
SUND				5, State Oil & Gas Lease No.
SUNDI	ere eranov zanovnom dri dom s o na propinska slakanim mala i kizara i sporovna a a d	MACARING COMMON TO THE STATE OF	The second secon	THE THE PROPERTY OF THE PARTY O
SUNDRY NOTICES AND REPORTS ON WELLS ON NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF PLUE BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCC PROPOSALS.)				
USE "APPLICA"	TION FOR PERMIT -" (FO	RM C-101; FOR SUCP PROPOSA	(VS)) вы вывысывает от настипация от вышениемого от общени вывыть	7. Unit Agreement Name
WELL GAS WELL OTHER. Water Injection			l .	Myers Langlie-Mattix U
ame of Operator				8. Farm or Leuse Name
kelly 0il Company				Myers Langlie-Mattix U
. O. Box 1351, Midland	1 Towns 7070	1		39
Location of Well	1, 1EAGO /3/U.	<u>Ab</u>	A THE STREET CONTRACTOR REGISSIONS SHOULD BE STREET TO STREET STREET, STREET STREET, S	10. Field and Pool, or Wildcat
UNIT LETTER M	660 FEET FROM	THE South LINE	45 660 FEET FROM	Langlie-Mattix
THE West LINE, SECT	10N 30 TO	OWNSHIP 238 HA	NGE 37E NMPM	
15, Elevation (Show whether DF, RT, GR, etc.)			CR, etc.)	12. County
		3343' DF	, ,	Les
Chack	Appropriate Boy		f Notice, Report or Ot	
	INTENTION TO:	To marche grande o	<del>-</del>	T REPORT OF:
			A	
PERFORM REMEDIAL WORK	FLUG	HIGSME.   NOGRABA DNA	AI WORK	ALTERING CASING
EMPORARILY ABANDON		·	ICE DRILLING OPNS.	PLUG AND ABANDONMENT
ULL OR ALTER CASING	CHÁN		TEST AND CEMENT JOB	Г
OTHER Convert to Water	er Injection	X	The same and some some of the source of the	
OTHER CONVERE ED WALE	ir rulection			
1) Move in workover ri 2) Clean out to 3650' 3) Run GR-N and collar 4) Set coated injection 5) Place well on injec	TD. r log 3000-365 on tubing and	0'. packer at 3440'.	-Mattix onen hole	3541-36501.