



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
HOBBS DISTRICT OFFICE

BRUCE KING
GOVERNOR
LARRY KILHOE
COMMISSIONER

POST OFFICE BOX 1000
HOBBS, NEW MEXICO 88240
505/331-6181

DATE: June 17, 1980

Getty Oil Company

P. O. Box 730

Hobbs, New Mexico 88240

Re: Plugging Reports

Attention:

Form C-103, Report of Plugging, for your Cowden #2-0 30-23-37
Lease Well No. Unit S-T-R
cannot be approved until a Commission representative has made an inspection of the location
and found it to be cleared to comply with Commission Rules and Regulations. Please check
each item in the space provided to indicate that the work has been done.

1. All pits have been filled and leveled.
2. Rat hole and cellar have been filled and leveled.
3. A steel marked 4" in diameter and approximately 4' above mean ground level has been set in concrete. It must show the quarter-quarter section or unit designation, section, township, and range numbers which have been permanently stencilled or welded on the marker.
4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
5. The dead men and tie downs have been cut and removed.
6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk and equipment.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Forms C-103 approved. When all of the work outlined above has been done, please notify this office by filling in the blank form below and returning this letter to us so that our representative will not have to make more than one trip to the location.

OIL CONSERVATION COMMISSION

Oil & Gas Inspector

FILL IN BELOW AND RETURN

I certify that the above work has been done and the location is ready for your inspection and approval.

Lease Well No. Unit S-T-R

Operator

Name and Title