

PLUGS AND ADAPTERS

Heaving plug—Material _____ Length _____ Depth set _____
 Adapters—Material _____ Size _____

SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
		Liquid TNT	45 qts	7/12/45	3572-88	3572-3620
		" "	50 "	"	3525-50	3525-3572

TOOLS USED

Rotary tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet
 Cable tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet

DATES

Put to producing _____ July 16, 1945
 The production for the first 24 hours was _____ barrels of fluid of which 100 % was oil; _____ %
 emulsion; _____ % water; and _____ % sediment. Gravity, °Bé. _____
 If gas well, cu. ft. per 24 hours _____ Gallons gasoline per 1,000 cu. ft. of gas _____
 Rock pressure, lbs. per sq. in. _____

EMPLOYEES

J. H. Mitchell, Driller
 Sam Gadberry, Driller
 Arthur Stine, Driller

FORMATION RECORD

FROM—	TO—	TOTAL FEET	FORMATION
0	36	36	Surface caliche
36	80	44	Surface sand
80	670	590	Red beds
670	721	51	Red beds and shells
721	1140	419	Red beds
1140	1250	110	Anhydrite
1250	1520	270	Salt
1520	1627	107	Salt and anhydrite
1627	1930	303	Salt
1930	2570	640	Salt and anhydrite
2570	2660	90	Salt
2660	2975	315	Anhydrite
2975	3050	75	Sand
3050	3090	40	Lime
3090	3118	28	Lime and anhydrite
3118	3299	181	Anhydrite
3299	3319	20	Lime
3319	3482	163	Anhydrite
3482	3505	23	Lime
3505	3517	12	Gypsum and lime
3517	3535	18	Lime
3535	3550	15	Sandy lime. Show gas 3535'-45'
3550	3567	17	Lime
3567	3574	7	Sand
3574	3574	0	Lime

FORMATION RECORD—Continued