

DUPLICATE

NEW MEXICO OIL CONSERVATION COMMISSION  
Santa Fe, New Mexico

## MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	<b>X</b>
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION  
SANTA FE, NEW MEXICOHobbs, New Mexico  
(Place)January 31, 1957  
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the

**Albert Gackle, Operator** **Cowden "C"** Well No. **5** in **G**  
(Company or Operator) (Unit)  
**SW** **NE** **31** **23S** **37E** **Langlie-Mattin** Pool  
(40-acre Subdivision)  
**Lea** County.

## FULL DETAILS OF PROPOSED PLAN OF WORK

(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

Clean out to TD, drill 30' of new hole using reverse circulation and oil for a circulating fluid, Run Caliper Survey. Set 200' of 4 1/2" liner on bottom and cement liner. Perforate selected intervals. Frac perforated intervals. Test well. Set pumping unit and place well on production

FEB 1 1957

Approved....., 19.....  
Except as follows:Approved  
OIL CONSERVATION COMMISSION

By

Title

E. J. Fischer  
Engineer District VII

Albert Gackle, Operator

By *Paul E. Johnston*  
Company or OperatorPosition **Superintendent of Production**

Send Communications regarding well to:

Name **Albert Gackle, Operator**Address **Box 2076 Hobbs, New Mexico**