UIL CONSERVATION DEL

P O. BOX 2086	Files (1+10)
The state of the s	रेसका इस्ट (13) है।
SANTA FE, NEW MEXICO 87501	
A FIRE	5 M. Matrare Type of Lease
23 0.3	Cinte X
LANC OFFICE	State Fee X
handle the second secon	, 5, State Oti & Gas Lease No.
GPERATOR	
	<u>i</u>
CHARDON POTICES AND DEPOSITS OF MELLIC	
SUNDRY NOTICES AND REPORTS ON WELLS	
TOO NOT USE THIS FORM FOR PROPOSACS TO DRICK ON IS DEEPER ON PLUG BACK TO A DIFFERENT RESERVOIR.	
1.	7. Unit Agreement Name
··	
orner Plugged & Abandoned Well	
2. Name of Operator	8. Form or Lease Name
	Cowden
Texaco Producing Inc. (Western Gas Co.)	Cowdell
3. Address of Operator	9. Weil No.
	1
P. O. Box 728, Hobbs, New Mexico, 88240	
4. Location of Well	10. Field and Pool, or Wildcut
- 220 %	
WHIT LETTER A 330 FEET FROM THE NORTH LINE AND 330 FEET FROM	
VALUE CONTRACTOR OF THE PROPERTY OF THE PROPER	
THE EAST LINE, SECTION 31 TOWNSHIP 23-S RANGE 37-E HMPM.	AIIIIIIIIIII
	VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
The state of the s	difficultiff the same of the s
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
2221 6 7	Lea
3321 G.L.	т пеа
TEMPORARILY ABANDON PULL OR ALTER CABING CHANGE PLANS CASING TEST AND CEMENT JQB OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	PLUE AND ABANDONMENT X
17. Describe Proposed or Completed Operations (Clearly State all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	estimated date of starting any proposed
Intent (C-103) was previously submitted 12-22-83 and approximate is a follow-up report on work done. No re-entry is partial. No injection will be commenced into Wells No. 41, 5 Myers Langlie Mattix Unit. 1-19-84 to 2-3-84: Rig-up pulling unit and install BOP. on 2-7/8" workstring, tag at 382', break circulation and be cellar. Rig down and repair hole in 13-3/8" surface casing ran 4-3/4" bit, tag @ 276'. Load hole with brine, broke of kick into casing, drop to 296'. Drill 3 hours, no progressione in hole. Ran magnet and then 4-3/4" concave mill, may be pull mill and ran 4-3/4" mill tooth bit. Drill on wood 29 free to 385'.Drill on wood and fill 401'-458' with 6 bits down all tools, rig down and move out. Well is temporarily	Run 4-3/4" bit had leak in hig. Rig-up and circulation and ss, left one (1) ill 296'-298'.
18. I hereny certify that the information above is true and complete to the best of my knowledge and belief. Digt Operations links	

EMP Com William

MAY 18'92

SEP 25 085