

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐

2. NAME OF OPERATOR  
TEXACO Inc.

3. ADDRESS OF OPERATOR  
P. O. Box 728, Hobbs, New Mexico 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 660' FSL & 1980' FEL  
AT TOP PROD. INTERVAL: (Unit Letter 'O')  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input checked="" type="checkbox"/>

(other) OF: ABANDON JALMAT ZONE

5. LEASE  
LC-032545 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
-

7. UNIT AGREEMENT NAME  
-

8. FARM OR LEASE NAME  
E. E. Blinebry Fed. 'B' NCT-1

9. WELL NO.  
4

10. FIELD OR WILDCAT NAME  
Jalmat Tansill Yates 7 Rivers

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 31, T-23-S, R-37-E

12. COUNTY OR PARISH 13. STATE  
Lea New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3124' (DF)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. RIGGED UP. INSTALL BOP. PULL TUBING FROM JALMAT ZONE.
2. SET CIBP @ 3280'. SET CEMENT RETAINER @ 2906'. CEMENT W/150 SX CLASS H CEMENT CONTAINING 5% HALAD 9. SQUEEZE W/ADDL 50 SX CLASS H CEMENT. WOC. DOC.
3. TESTED SQUEEZE JOB TO 600# FOR 30 MINUTES. TESTED OK.
4. DRILL OUT CIBP @ 3398'.
5. RUN 2 3/8" TUBING W/ PKR AND SET @ 3424'.
6. REMEDIAL WORK COMPLETED W/JALMAT YATES ZONE ABANDONED, 9-19-84, AND LANGLIE MATTIX TO WATER INJECTION.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED \_\_\_\_\_ TITLE Asst. Dist. Mgr. DATE 9-19-84

ACCEPTED FOR RECORD (This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

OCT 3 1984

Carlsbad, NEW MEXICO

\*See Instructions on Reverse Side