

OXY USA WTP LP

MYERS LANGLIE MATTIX NO. 95 (Tubing Leak Repair)
SEC 31 T23S R37E Lea, NM

05/11/1995 CMIC:Mulkey

This well is a dual completion w/ Texaco's EE Blinebry "A" Fed. #2
We have developed a tbq or packer leak which has killed there well, 20 MCFD.

05/19/1995 CMIC:Zuniga

Notified Cliff Johnson w/ Texaco prior to rigging up pulling unit.
MIRU ND WH. NU BOP. Released off Baker parallel snap latch seal nipple,
POOH w/ 98 jt's of 2 1/16" 10 rd thd tbq. (Texaco short string). No
External corrosion or pits on tbq. released off Baker seal Assy,
POOH w/ 88 jt's of 2 1/16" 10 rd IPC tbq and Baker Model "K" Double Grip Packer
and 12 jt's 2 1/16" 10 rd internally and externally plastic coating tbq, Baker
FL On-Off tool w/ 1.50 BFC Profile, 1- 6' pup joint, Baker Model L Sliding
Sleeve, Baker Model E Anchor tbq seal Assembly. (OXY Long string).
No External Corrosion or pits on tbq. Baker oil tools to redress and
repair Packer and Seal Assy. SION.

Note: Unit Cost: \$ 1185.00

BOP, Spool, Slip type elevators: \$ 565.00 (5 day min)

L/E: \$1750 CUM L/E: \$1750

05/20/1995 CMIC:Zuniga

Baker oil tools repaired Packer and redressed seal Assy. Found small
hole in Model E Anchor seal assembly. Will run tbq inj tbq this AM.
CUM L/E: \$1750

05/21/1995 CMIC:Zuniga

RU phils tbq tester. RIH w/ 2 1/16" inj tbq as follows: (Long string)
1- 2 1/16" x 1.43 BFC Model R SN w/ 2 1/16" 10 rd thd box and pin-.81
1- 2 1/16" 10 rd x 6' pup joint, inter& exter PC- 6.06
1- 2 3/8" 10 rd x 2 1/16" 10 rd, inter & exter PC swage- .62
1- Baker Model "E" Seal Assy w/ 2 seal units - 2.47
1- 2 3/8" x 6' pup joint, inter & exter PC - 6.10
1- 2 3/8" x 3' pup joint, inter & exter PC - 3.16
1- 4 1/2" x 2 3/8" Baker FL On-Off w/ sealing connector,
w/ 2 3/8" 8rd thd box & pin w/ 1.50 BFC Profile- 1.63
1- 2 1/16" 10 rd x 2 3/8" 8rd inter & exter PC swage- .69
12- jt's 2 1/16" 10 rd inter & exter PC tbq- 388.48
1- Baker Model K Double Grip Snap set Ret Dual Pkr IPC- 8.81
88- jt's 2 1/16" 10 rd 3.40# IPC tbq- 2852.71
4- 2 1/16" 10 rd 3.40# IPC tbq subs - 28.47
TP - 3300.01
KB - 10.00

TP set @ - 3310.01. Sting into Model D pkr w/ seal assy @ 3300'. Tested tbq
above slips to 3500#. Tested Ok. No leak found. RIH w/ short string as
follows:

1- Baker Model S Parallel Snap Latch Seal Nipple- 11.60
98- jt's 2 1/16" 10 rd 3.40# tbq (Non-Coated)- 2886.18
Tested tbq to 3500# above slips, Tested Ok. No leak found. RD tbq tester. RU
Kill Truck, pumped 64 bbls packer fluid. (Cap to Pkr 62 bbls). Lower tbq and
latch into Baker Model K Dual Pkr. loaded csg w/ packer fluid. ND BOP. NU
Wellhead. Installed chart recorder. Press csg to 340 psi. Couldn't get a
good chart, indicating air trap. Tried 3 times, same. RD Kill Truck. Close
well in. SD until Monday.
Note: Unit cost: \$1455.00 Kill truck: \$515.00 Phils tester: \$1072.72
L/E: \$3043 CUM L/E: \$4793

05/22/1995 CMIC:Zuniga

SD for Sunday.

L/E: \$0 CUM L/E: \$4793