


SCOUT REPORT NEW MEXICO

OIL CONSERVATION COMMISSION

(Gulf-Western)



Company Great Western Producers

Farm Name Harry Leonard Well No. 1

Land Classification State

Sec. 32 Twp. 23 Range 37 County Lea

Feet from Line: 1980 N. 660 E. W.

Elevation _____ Method fatigue

Contractor Livermore Scout L.

Spudded 8-14-38 Completed 9-14-38 Initial Production

Bond Status

Gulf Farmout

ACID RECORD

Casing and Cementing Record Amount

Size	Feet	Inches	Sex Cement
20	20		60
15 1/2	120		100
12 1/2	192		150
10 3/4	215		100
7	3300		500
2	3596		

Gals.

500

Prod.

Date

Prod.

Date

Top Pay 3560

Total Depth

SHOOTING RECORD

No. of Quarts 215

Shot at 3500

Feet 3595

No. of Quarts

Shot at

Feet

Date		Date	
6-22	<u>Loc</u>	SEP 7 - 1938	<u>T.D. 3615 L</u>
7-5	<u>✓</u>		<u>prep to clean out</u>
JUL 12 1938	<u>C & P M.I.M.</u>		<u>Swabbed dry</u>
JUL 19 1938	<u>T.D. 192 RR.</u>		<u>75 M Gas</u>
	<u>Rug 15 1/2</u>		<u>Blew out w/ M-2 Gas</u>
JUL 26 1938	<u>T.D. 215 RR. W.C.</u>		<u>prep to shoot.</u>
AUG 2 - 1938	<u>T.D. 252 RR. WOC</u>	SEP 12 1938	<u>T.D. 3615 L</u>
AUG 9 - 1938	<u>φ 1662 X & H</u>		<u>Tst g.</u>
AUG 15 1938	<u>φ 3092 L</u>		<u>Cleaned out</u>
	<u>5/8 2690-94</u>		<u>1 1/2 Gas</u>
AUG 23 1938	<u>T.D. 3350 L</u>		<u>16 Bo & low</u>
	<u>WOC.</u>		<u>1/2 choke</u>
AUG 30 1938	<u>T.D. 3492 Sack</u>	SEP 19 1938	<u>T.D. 3615 L</u>
	<u>15 M-2 Gas</u>		<u>I.D. F 40130 PD</u>
	<u>3487-92</u>		<u>1/2" Choke</u>
	<u>To Drill Rhoe</u>		<u>2" Tbg</u>
	<u>SLM 2472</u>		<u>240 M Gas</u>

LOG

[illegible]