

OIL CONSERVATION COMMISSION

Company Great Western
Farm Name Harry Leonard B. Well No. 2
Land Classification _____
Sec. 32 Twp. 23 Range 37 County Nea
Feet from Line: 660 N. S. E. 660 W.
Elevation _____ Method Rotary
Contractor Wivernore Scout
Spudded 3/24 Completed 4/1 Initial Production _____
Bond Status _____


Date	Date
3-7-39 Derrick	
MAR 14 1939	APR 25 1939 T.D. 300 AL P.E. 20 19
MAR 21 1939	L.P. 97 20 PD
MAR 28 1939	
APR 4 1939	
APR 11 1939	
APR 18 1939	

ILLEGIBLE

LOG

[illegible]

SCOUT REPORT NEW MEXICO OIL CONSERVATION COMMISSION



Company Great Western
 Farm Name Harry Leonard B. Well No. 2
 Land Classification _____
 Sec. 32 Twp. 23 Range 37 County NGA
 Feet from Line: 660 N. S. E. 660 W.
 Elevation _____ Method Rotary
 Contractor Wivernore Scout _____
 Spudded 3-24 Completed 4-24 Initial Production _____
 Bond Status _____

ACID RECORD

Casing and Cementing Record Amount

Size	Feet	Inches	Sax Cement
<u>8 5/8</u>	<u>1200</u>		<u>500</u>
<u>5 1/2</u>	<u>3470</u>		<u>200</u>
<u>2 1/2</u>	<u>3570</u>	<u>perf</u>	<u>3510</u>

Gals.

	Prod.	Date
	Prod.	Date
Top Pay <u>3495</u>	Total Depth	

SHOOTING RECORD

No. of Quarts <u>140</u>	Shot at <u>3510</u>	Feet <u>3579</u>
No. of Quarts	Shot at	Feet

Date		Date	
<u>3-7-39</u> <u>Derrick</u>		<u>APR 25 1939</u>	<u>SLM 3595-299</u>
<u>MAR 14 1939</u>	<u>no data.</u>		<u>T.D. 36246</u>
<u>MAR 21 1939</u>	<u>Derrick</u>		<u>P.B. 3579</u>
<u>MAR 28 1939</u>	<u>T.D. 1211H</u>		<u>I.P. 9780 P.D.</u>
	<u>WOC</u>		<u>3/16 "4"</u>
<u>APR 1 - 1939</u>	<u>3105 L + A</u>		
<u>APR 1 - 1939</u>	<u>T.D. 3496 shy L</u>		
	<u>WOC</u>		
	<u>SLM 3494-96</u>		
<u>APR 18 1939</u>	<u>T.D. 36246</u>		
	<u>Tatq.</u>		
	<u>BDP + Cap</u>		
	<u>9-19- 39 BOPD</u>		
	<u>15 - 36 BOPD</u>		
	<u>16 - 30 ✓</u>		
	<u>17 - 27 ✓</u>		
	<u>555 M Grad</u>		
	<u>to shoot.</u>		

LOG

[illegible]