

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANITARY	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

0+1 —

P.O. BOX 1980
HOBBS, N.M. 88240 (LEA COUNTY)

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSED TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PURPOSES.

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER- Plugged & abandoned well

2. Name of Operator
Getty Oil Company

3. Address of Operator
P. O. Box 730, Hobbs, New Mexico 88240

4. Location of Well
UNIT LETTER B 660 FEET FROM THE North LINE AND 1980 FEET FROM
THE East LINE, SECTION 33 TOWNSHIP ILLEGIBLE N.M.P.M.

15. Elevation (Show whether DT, RT, GK, etc.)

7. Unit Agreement Name

8. Form or Lease Name
Fanning

9. Well No.
2

10. Field and Pool, or Wildcat

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	1-R.J. STARRAK-TULSA
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	1-A.B. CARY-MIDLAND
PULL OR ALTER CASING ☐		1-E. Buttross, ENGINEER
		1-H.C. Little, FOREMAN - MLMU
OTHER <u>Reenter and replug</u> ☒		1-FILE
		Q- <u> </u> , WIO's -LIST ATTACHED
		1-BH, FIELD CLERK

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

According to the NMOC Order No. 460 for the expansion of our Myers Langlie Mattix Unit, this well must be properly plugged before water can be injected within a 1/2 mile radius. We plan to reenter and replug the well using the following procedure:

1. Rig up pulling unit and install BOP.
2. Drill out cement plugs surface-20', 1035-1075', and 2850-2900'.
3. Displace hole with 10% mud.
4. Spot 40 sxs. cement plug 3310-3410' over 7" casing cutoff at 3360'.
5. Spot 40 sxs. cement plug 2900-3000' over 9 5/8 casing shoe at 2950'.
6. Spot 70 sxs. cement plug 1450-1550' over 9 5/8 casing cutoff at 1500'.
7. Spot 100 sxs. cement plug 268'-368' over 13 3/8 casing shoe at 318'.
8. Spot 70 sxs. cement plug surface-50'.
9. Set marker.

THE COMMISSION MUST BE NOTIFIED
24 HOURS PRIOR TO COMMENCING WORK

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Area Superintendent DATE 8-17-78

APPROVED BY Jerry Seaton TITLE Dist. I, Supv. DATE AUG 21 1978

CONDITIONS OF APPROVAL, IF ANY: