

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions
reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. LC-064118
2. NAME OF OPERATOR Plains Petroleum Operating Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 415 West Wall, Suite 1000, Midland, TX 79701		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit a, 660' FNL & 810' FEL		8. FARM OR LEASE NAME Eva E. Blinbry
14. PERMIT NO.		9. WELL NO. #8
15. ELEVATIONS (Show whether DF, RT, CR, etc.) 3268' DF		10. FIELD AND POOL, OR WILDCAT Langlie Mattix 7RVS QN GB
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 34, T23S, R37E
		12. COUNTY OR PARISH Lea
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to cleanout wellbore with bit to TD @ 3538' to remove scale, fill, and junk equipment in bottom of well. After cleaned out, propose to run 4-1/2" liner in OH section of well (will overlap bottom of casing), and then acidize Seven Rivers-Queen OH with 5000 gals 15% NEFE HCl acid.

18. I hereby certify that the foregoing is true and correct		Petroleum Engineer	March 31, 1993
SIGNED <u>Mark Thierherding by ddy</u>	TITLE	DATE	
(This space for Federal or State office use)			
APPROVED BY <u>(Signature)</u>	TITLE <u>PETROLEUM ENGINEER</u>	DATE <u>4/22/93</u>	
CONDITIONS OF APPROVAL, IF ANY:			

*See Instructions on Reverse Side