UNIT STATES SUBMIT IN TRIPL (Other Instructions OF THE INTERIOR (Other Instructions) OF THE INTERIOR (Other Instructions)	JIC Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.
(May 1963) OTHER PARTMENT OF THE INTERIOR (Other instructions verse side) GEOLOGICAL SURVEY	Las Cruces 064118
SUNDRY NOTICES AND REPORTS ON WELLS not use this form for proposals to drill or to deepen or plug back to a different reservoir Use "APPLICATION FOR PERMIT—" for such proposals.)	
OIL GAS OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME E.C.Hill "B" Federal
Carter Foundation Production Company 3. ADDRESS OF OPERATOR	9. WELL NO.
P. O. Box 900, Kermit, Texas 79745	3
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) 	Toogue Plinebry
840' FNL & 1655.5' FEL, Section 34, T-23-S,	Teague Blinebry 11. sec., T., B., M., OR BLK. AND
R-37-E, Lea County, New Mexico	Sec. 34, T-23-S, R-37-E
At monopolic (Oh., which are the A	12. COUNTY OF PARISH 13. STATE
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3273 DF	Lea NM
16. Check Appropriate Box To Indicate Nature of Notice, Repo	ort, or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATME SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZ	<u>v</u>
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDI: REPAIR WELL CHANGE PLANS (Other)	
(Other) Completion or	rt results of multiple completion on Well r Recompletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertine proposed work. If well is directionally drilled, give subsurface locations and measured and tr nent to this work.)*	ent dates, including estimated date of starting any ue vertical depths for all markers and zones perti-
1. Installed blowout preventer. Pulled tubing and pac	eker.
 Acidized with 5,000 gals. 15% Neat acid and 40 ball in at 2 bbls. per minute at 100# pressure. Raised minute at 500#; raised rate to 4 bbls. at average pre Pumped in acid, followed with 27 bbls. flush. 	rate to 3 bbls. per
3. Swabbed well.	
4. Put on entermeter.	
	10 EGETWE 10 AUG 1 9 1981 11
	OIL & GAS U.S. GEOLOGICAL SURVEY COSWILL, HINY MEXICO
18. I hereby certify that the foregoin as true and correct SIGNED Agent	DATE 8-14-81
(This space for Federal or State office use)	ACCEPTED FOR RECORD
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE
	AUG 30 1981

*See Instructions on Reverse Side

U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO