Form 3160-5 UNI (December 1989) DEPARTMEN BUREAU OF	FORM APPROVED Budget Bureau No. 1004-0135 Expires: September 30, 1990 S. Lease Designation and Serial No.	
SUNDRY NOTICES Do not use this form for proposals to d Use "APPLICATION FO	LC- 060825B 6. If Indian, Attonce or Tribe Name	
I. Type of Well	7. If Unit or CA. Agreement Designation	
Vell       Gas Well       Other         2. Name of Operator <u>Texaco Exploration &amp; Produ</u> 3. Address and Telephone No.         P.O. Box 730, Hobbs, NM         4. Location of Well (Footage, Sec., T., R., M., or Survey D Unit E, 1980 FNL, 660 FWL Sec. 34, T-23-S, R-37-E	88241-0730 (505) 393-7191	<ul> <li>8. Well Name and No. Myers <ul> <li>Langlie Mattix Unit #83</li> </ul> </li> <li>9. API Well No. <ul> <li>30-025-10955</li> </ul> </li> <li>10. Field and Pool, or Exploratory Area <ul> <li>Langlie Mattix 7R Queen</li> </ul> </li> <li>11. County or Parish, State <ul> <li>Lea County, NM</li> </ul> </li> <li>PRT, OR OTHER DATA</li> </ul>
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment  Recompletion  Plugging Back Casing Repair  Attering Casing Other	Change of Plans Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection
give subsurface locations and measured and true vertic	(Note: Report results Recompletion Report Il pertinent details, and give pertinent dates, including estimated date of startis cal depths for all markers and zones pertinent to this work.)*	ag any proposed work. If well is directionally drilled,

- Rig up unit, install bop. TIH with tubing and tag CIBP. 2)
- Load hole with salt gel mud; 10# brine and 25# gel/ Bbl. 3)
- Pump 20 sx plug from 2200'-2300'. WOC and tag plug. 4)
- By wireline, perf 2 squeeze holes at 1200'. 5)
- GIH with tubing. Establish circulation through perfs and pump 30 sx class 6) "C" cement from 1100' to 1200'. WOC and tag plug.
- Perf 2 squeeze holes at 380. Establish circulation and pump 100 sx 7) cement. Fill casing and annulus to surface. Cutoff wellhead and install marker. Clean location.
- 8)

I hereby certify shat the foregoing is true and correct Signed	Title Production Engineer	Date
(This space for Federal or State office use)	person at Factoria	· · ·
Approved by Conditions of approval, if any:	Tide	Date <u>4(3/92</u>

		WE	ELL_DATA_SHEET PO-1: (3/92
OPERATOR:	Te:	xaco_E&P_Inc.	Lease: <u>Myers Langlie Mattix Unit</u> #83
FOOTAGE LO	CATION	: <u>1980 FNL X 660 FWL</u> 8	Sec./Twn/Rng: <u>Unit E, Sec 34, T-23-S, R-37-E</u>
<u>Former Te</u>	exas Pa	cific Blinebry 'B' #5	Lea County, New Mexico
	HEMATIC		TABULAR DATA
			Surface Casing: Set at330'
Gr	330' 2230' 3150'	3275' GL	Size <u>8 5/8, 24</u> Cemented with <u>300</u> sx
330'		8-5/8", 24#, 300 sx, cement circulated	
: }		Coment Circuiateu	Hole Size?? Comp. Date7-13-61
. 2230'		TOC, temp.	Intermediate casing: Set at
		100, cemp.	Size <u>NONE</u> Cemented withsx
3150		CIBP, 35' cement	TOC ' determined by
3616			Hole Size
•		5-1/2", 14#, 300 sx, TOC @ 2230'	Production Casing: Set at
•			Size <u>5 1/2", 14#</u> Cemented with <u>300</u> sx
Tops:		0'-2360' 9'	TOC
	1200' 2359'		Hole Size <u>7.7/8"</u>
7 Rivers Queen			Present Completion:
2			<u>_3225</u> ' to <u>_3562</u> ' <u>perfs, 1-4 SPF</u>

PO-113 PLUG AND ABANDON DATA (3/92) OPERATOR: \_\_\_\_\_ Texaco E&P Inc.\_\_ FOOTAGE LOCATION: 1980 FNL X 660 FWL Sec./Twn/Rng: Unit E, Sec 34, T-23-S, R-37-E <u>Classified TRO on 12-12-88, CIBP set at 3150'</u> <u>Lea County, New Mexico</u> SCHEMATIC PLUGGING DATA Surface Plug: Gr Size <u>380'-surf.</u> Cemented with <u>100</u>sx. 330'-Surface, 330' 100 sx. Includes 10% extra cement volume. Class 'C' Cement, 1.32 cu ft/ sx 1200' T/Salt, 30 sx, 1100'-1200' Intermediate Plug(s): • Size <u>1100'-1200'</u> Cemented with <u>30</u> \_sx. 2230' TOC, 20 sx, 2200'-2300' 20 2200/-2300/ . SX Class 'C' cement, 1.32 cu ft/ sx 3150' CIBP, 35' Producing Zone Plugs: .) 3616' Size <u>CIBP, 35'</u> Cemented with Angle Sx ????