

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLI
(Other instructions
reverse side)

5-
FE-

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ FEB 9 11 03 AM '93

2. NAME OF OPERATOR
Plains Petroleum Operating Company

CARL
AREA

3. ADDRESS OF OPERATOR
415 West Wall, Suite 1000, Midland, TX 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit C, 330' FNL & 1660' FWL

14. PERMIT NO.

30-025-10965

15. ELEVATIONS (Show whether OP, RT, CR, etc.)

325' IF

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

LC-064118

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Eva E. Blinebry

9. WELL NO.
#10

10. FIELD AND POOL, OR WILDCAT
Langlie Mattix 7RVS QN

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 35, T23S, R37E

12. COUNTY OR PARISH 13. STATE
Lea NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PCLL OR ALTER CASING

☐
☐
☐
☐
☐

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☒
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐
☐

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROMISED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

01-22-93 MIRUSU. Parted coupling 12 RFS. ND wellhead. NU BOP. RIH w/tbg, fill @ 3532' (4' fill). PU & RIH w/6-1/8" mill tooth bit, bit sub, (6) 4-3/4" DC, XO, 2-3/8" hydril tbg, left bit @ 3400'. Close BOP, SDFN.

01-23-93 Open BOP, RIH w/tbg, tag up @ 3511'. Drill to 3555'. RU acidizers & spot acid over open hole. POOH. PU & RIH w/1 jt 2-3/8" tbg, 2-3/8" X 7" pkr, 2-3/8" SN, 104 jts hydril tbg. Set pkr @ 3413' w/18000# tension. Acidize zone w/5000 gals 15% NeFe HCl dropping 1500# salt block in 3 stages. Flush w/17 BPW. Release pkr, SDFN.

01-24-93 SICP 125#. Open BOP. POOH & LD pkr. RIH w/2-3/8" BPMA, 2-3/8" perf'd tbg sub, 2-3/8" SN, 113 jts 2-3/8" tbg. ND BOP, NU wellhead. RIH w/new 2" X 1-1/2" X 12' pump (139) 3/4" rods, 3/4" X 4' pony rod, 1-1/4" X 12' polished rod. RDMOSU.

David A. Glass
ONLINE MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Theresa A. Anderson

TITLE

Petroleum Engineer

DATE

February 8, 1993

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side