

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instruction
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

030176-B - Las Cruces

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

C. C. Cagle "C"

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Grosby Devonian11. SEC. T., R., M., OR BLEK. AND
SURVEY OR AREA**Sec. 3, T-26-S, R-37-E**

12. COUNTY OR PARISH

Lea13. STATE
New Mexico1. OIL ☐ GAS ☒ OTHER
WELL WELL

2. NAME OF OPERATOR

Amerada Petroleum Corporation

3. ADDRESS OF OPERATOR

P. O. Box 668 - Hobbs, New Mexico4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface**660' FWL and 660' FWL of Sec. 3**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3004' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)***Well was temporarily abandoned 12-12-63.****February, 1964, pulled tubing and packer. Squeezed 5-1/2" casing perforations from 8670' to 8710' with 100 sacks slo-set cement. Checked top of cement at 8640'. Perforated 5-1/2" casing from 8580' to 8610' and 8620' to 8625' with 1 shot per foot. Acidized perforations with 300 gals. 15% HCl acid. Swabbed dry. No show of gas. Acidized perforations with 2000 gals. 15% HCl acid. Swabbed dry. No show of gas. Squeezed perforations from 8580' to 8610' and 8620' to 8625' with 75 sacks slo-set cement. Top of cement at approximately 8544'. Pulled tubing and closed well in.****Propose to plug and abandon as follows: Cut 5-1/2" OD casing at approx. 6000'. Spot cement plug in top of cut off 5-1/2" casing. Spot cement plug in bottom of 8-5/8" casing at 2200'. Cut off 8-5/8" casing at approx. 2000'. Spot cement plug in top of Salt from approx. 1000' to 1100'. Spot cement plug in base of 13-3/8" casing at 640'. Spot plug in top of 13-3/8" casing with dry hole marker. Mud will be between plugs.****NOTE: This confirms verbal approval from Mr. A. R. Brown, U.S.G.S. 8-24-64.**

18. I hereby certify that the foregoing is true and correct

SIGNED

W. L. C. J. J. C.

TITLE

District Superintendent

DATE

8-24-64

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side



Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

SEP 1 11 47 AM '64
RECEIVED
FEDERAL BUREAU OF INVESTIGATION
U.S. DEPARTMENT OF JUSTICE