

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

STANDARD FORM NO. 100
MAY 1962 EDITION
GSA GEN. REG. NO. 25

Form approved
Interior Department No. 42 R1424.
PLEASE DESIGNATE AND SERIAL NO.

LG 054668

U. S. INDIAN, ALIEN, OR PRIDE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Notice of Intent to drill or to deepen or plug back to a different reservoir.
(See "REGULATIONS FOR PERMIT" for such proposals.)

9. DATE '66

7. UNIT AGREEMENT NAME

8. NAME OF LEASE NAME

NORTH C FEDERAL

9. WELL NO.

7

10. FIELD AND POOL, OR WILDCAT

CROSBY DEVONIAN GAS

11. SEC., T., R., M., OR BLM, AND
SULVEY OR AREA

4-26-37 NMPPM

12. NAME OF OPERATOR

13. ADDRESS OF OPERATOR

Biggs, Hobbs, New Mexico 88240

(See "REGULATIONS FOR PERMIT" for location clearly and in accordance with any State requirements.)

660 FNL * 1980 FWL, Sec. 4 (UNIT C NE/4 NW/4)

14. COUNTY NO.

15. ELEVATIONS (SHOW WHETHER EF, ST, OR, etc.)

3004' R.D.TS.

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

WATER SHUT-OFF

FRAC TREATMENT

SHOOTING OR ACIDIZING

REPAIRING WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

☐
☐
☒
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRAC TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. Describe in detail all completed operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any operations, if well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to the operations.)

Well is no longer capable of producing from the reservoir and is shut-in. Workover or recompletion possibilities are not feasible. Propose to plug and abandon as follows:

Spot 25 cu. Cement plug 3650 to 3750' (logs 8778 - 8759)

Sheet and pull 5 1/2" (est. 3' approx. 6500')

Cement plugs @:

20 cu. 6550-6450 (Int. out of 5 1/2" slot)

25 cu. 6300 - 6200

40 cu. 4100 - 3850 (8 5/8" CSA 3881)

10 cu. Surface and track P&A markers.

Make final cleanup and restore ground to contour.

TD-2915, PSD-8791,

13 5/8" CSA 3881, 8 5/8" CSA 3881, 5 1/2" CSA 3881, 7 1/2" CSA 3881, 7 1/2" CSA 3881

18. I, the undersigned, declare the foregoing is true and correct

SIGNED

TITLE

DATE 9-16-66

(This space is reserved for State office use)

APPROVED BY

TITLE

DATE

REMARKS ON APPROVAL, IF ANY:

*See Instructions on Reverse Side

