

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Los Cruces
Lease No. 062384
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 12, 1950

Well No. 4 is located 660 ft. from N line and 1980 ft. from E line of sec. 13

Sec. 13 263 373 N.M.P.
(4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
South Leonard (Hrt.) Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On July 11, 1950, at 6:00 P.M., 4 hours after pipe was mudded, the hole was bailed dry immediately after mudding and during this test no fluid entered the hole. The test is considered satisfactory. Drilled ahead with 8" bit. *at 105'*

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Leonard Oil Company

Address P. O. Box 572

Roswell, New Mexico

By Emmanuel White

Title Vice-President