

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
verse side)E*
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 030200-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☒ GAS ☐
WELL WELL OTHER

2. NAME OF OPERATOR

Pan American Petroleum Corporation

3. ADDRESS OF OPERATOR

Box 68 - Hobbs, New Mexico - 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

680' FWL X 660' FWL, Sec. 18 (Unit D, NW/4 NW/4)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

C.M. Farnsworth "A"

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Jalmit (Oil)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

18-26-37 NEPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

2957' DF

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☒
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

In accordance with 9-331 submitted 7-2-64, abandonment operations performed as follows:

1. Spotted 25 sx cement plug across perforations 3123-28'.
2. Cut and pulled 7" casing from approx. 1600'. (attempted cuts at 2200' and 1800')
3. Spotted 30 sx cement plug in and out of 7" casing stub at 1600'.
4. Cut and pulled 9-5/8" casing from approx. 1200'.
5. Spotted 30 sx cement in and out of 9-5/8" stub at 1200'.
6. Spotted 30 sx cement plug in and out of 13-3/8" shoe at 482'.
7. Spotted 10 sx cement plug at surface and erected FIA marker

All intervals filled with heavy mud laden fluid.
Location cleared and restored ground to contour.

P I A 00 8-1-64. Comp. 8-4-64.

18. I hereby certify that the foregoing is true and correct

Original Signed by:

SIGNED L. E. STALEYTITLE Area SuperintendentDATE 9/22/64

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

APPROVED _____

SEP 4 1964

*See Instructions on Reverse Side

J. L. GORDON

ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.