

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN
(Other inst.
verse side)

PLICATE*
ons on re-

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. <u>LC-030168A</u>
2. NAME OF OPERATOR <u>Conoco Inc.</u>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <u>P.O. Box 460 - Hobbs, New Mexico 88240</u>	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>330' FSL & 2310' FFL - Unit Letter D</u>	8. FARM OR LEASE NAME <u>Jones A</u>
	9. WELL NO. <u>No. 1</u>
	10. FIELD AND POOL, OR WILDCAT <u>WMEC/Scarbrough Yates</u>
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>19-26S-37E 7 RVS</u>
14. PERMIT NO. <u>30-025-12007</u>	12. COUNTY OR PARISH <u>Lea</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRR
2. Go in hole to CIBP at 2800'.
3. Load & circulate with 164 bbls 9.5 ppq mud (9.0 ppq brine plus 25 sxs gel / 100 bbls brine). Pressure test casing to 300 psi.
4. Spot 70 sxs cement plug on top of CIBP. Displace w/ 14.6 bbls of 9.5 ppq mud. Top of plug at 2530'. POOH.
5. Perforate through both strings at 1120' with 4 shots.
6. Establish circulation down casing & circulate surface cement plug in 8 5/8", 10 3/4" & 16" casing w/ 1500 sxs cement. Bull head 325 sxs cement down 16" annulus.
7. Install P&A marker

18. I hereby certify that the foregoing is true and correct

SIGNED Walter H. Finney, Jr.

TITLE Administrative Supervisor

DATE October 12, 1987

(This space for general or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE 11-9-87

*See instructions on Reverse Side

Title 18 U.S.C. section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) ARCO (2) Amoco (2) Chevron (1) File