

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI
(Other instructio
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Eaves A
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, NM 88240	9. WELL NO. 5
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 1980' FWL (Unit Letter K)	10. FIELD AND POOL, OR WILDCAT Scarbrough Unit 7 Rvrs
11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA 19-26S-37E	12. COUNTY OR PARISH Dea
13. STATE NM	
14. PERMIT NO. 30-025-12011	15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Open & Test Add'l Pkgs

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

MIRU. Tag up at 3217'. Log from 3217'-2400'. Cmt band good. Set RBP at 3107'. Test to 1000 psi. Press test csg to 500 psi. Perf SR 1, 2 & 3 interval & acidize w/ 2 bbls 15% HCL-NE-FE acid from 3106'-3024' w/ 17.5 bbls 9" brine. POC H. Perf at 3042' to 3104' for total of 12 shots & 24 holes. Set pkr at 3013' & test to 500 psi & monitored. Acidized SR 1, 2 & 3 perfs w/ 48 bbls 15% HCL-NE-FE acid, dropping 2 7/8" RCN 13 SG ball sealers after each 2 bbls of acid pumped, 3 balls on last 2 drops (48 ball sealers total) Flush to bottom perfs w/ 19.6 bbls 9" brine. Swab well. Set RBP & test to 1000 psi. Acidized w/ 2 bbls 15% HCL-NE-FE acid from 3036'-2954'. Perforate & rig down. Set pkr at 2920'. Acidize Yates perfs w/ 56 bbls 15% HCL-NE-FE acid. Flush to bottom perfs w/ 19.7 bbls 9" brine. Rel pkr. Latch on RBP

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Asst. Dir.

DATE March 27, 1987

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE

APR 2 1987

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad(6) ARCO(2) Amoco(2) Chevron(1) File

RECEIVED
APR 7 1987
OCD
HOBBS OFFICE