

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other instructions
reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. LC-030168(A)
2. NAME OF OPERATOR CONOCO INC.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit N	8. FARM OR LEASE NAME Eaves A
14. PERMIT NO. 30-025-12012	9. WELL NO. 8
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	10. FIELD AND POOL, OR WILDCAT Scarborough Yates Seven Rivers
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 19-26S-37E
	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

open add'l pay

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- ① MIRU on 1/23/86.
- ② Set RBP @ 3077', test to 1000 psi. Spot 2 bbls 15% HCL, Perf w/ 2 JSPF @ 3026', 22', 26', 30', 32', 38', 45', 48', 54', 61'. Set pkr @ 2908' and acidize w/ 44 bbls 15% HCL.
- ③ Swab and pump test, zone did not prove commercial.
- ④ Set RBP @ 3085' & test to 1000 psi. Dump 25 sxs sand on top. Set ret. @ 2930', sqz perfs 3026'-3061' w/ 50 sxs class "C" w/ 2% CaCl₂ + .6% Halad-9. Tag cmt @ 2923', DO to 2994' and fell thru. Tag @ 3050' & drilled to 3080'.
- ⑤ Set pkr @ 2930' and test sqz. Sqz didn't hold.
- ⑥ Set retainer @ 2903' and pumped 50 sxs class "C" w/ 2% CaCl₂ and tail-in w/ 100 sxs class "C" w/ 2% CaCl₂. Drilled out cmt to 3070'. Circ. sand off RBP. Test csq to 700 psi & held ok.
- ⑦ With w/ ret. tool, Circ. trash off RBP. Reset RBP @ 3021' & test to 1000 psi. Spot 2 bbls 15% HCL from 3010'-2992'. Perf w/ 2 JSPF from 2992'-98' & 3006'-10'. Set pkr @ 2901'. Acidized w/ 48 bbls 15% HCL. Flushed acid. Swab, zone did not prove commercial.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Administrative Supervisor

DATE

2-10-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

SWR

FEB 11 1986

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

CARLSBAD, NEW MEXICO

BLM - Carlsbad (6) ARCO (2) AMOCO (2) chevron (1) File

RECEIVED
FEB 14 1986
O.C.O.
HOBBS OFFICE