

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRI-
(Other Instruction on re-
verse side)

FORM TO O. C. C.

Form approved.
Budget Bureau No. 42-R1124.
5. LEASE DESIGNATION AND SERIAL NO.

LC 050168 (A)
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Salt water Disposal well

2. NAME OF OPERATOR
Continental Oil Company

3. ADDRESS OF OPERATOR
P. O. Box 460, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FSL 4990' FEL, Sec. 19, T-26S, R-37E,

Dea County, N. Mex.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

2938' GL

7. UNIT AGREEMENT NAME

N. M. F. V.

8. FARM OR LEASE NAME

Cross A

9. WELL NO.

10

10. FIELD AND POOL, OR WILDCAT

Galveston pool

2 SEC. T. E. M. FOR BLK. AND
SUEVEY GR AREA

Sec. 19, T-26S, R-37E

12. COUNTY OR PARISH

Dea

13. STATE
N. Mex

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Convert to SWP

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

This well was converted to a salt water disposal well by the following procedure:

Squeezed plugs from 3107' to 3182'. Drilled out cement and CIBP at 3200' and cleaned out to 3251'. Perforated from 3208' to 3251' with 2 jet shots per foot. Ran 3 1/2" plastic lined tubing with tension packer and set packer at 3195'. Treated plugs with 2,000 gals. 15% HCL Acid.

Well ready to start injecting salt water.

USGS-5, Alb. River, Permian Hobbs 2, Chem. mid 2, Fide

18. I hereby certify that the foregoing is true and correct

SIGNED W. E. Whalley

TITLE Administrative Section Chief

DATE 12-16-68

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DEC 26 1968

A. R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side