

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN
(Other instr. apply on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Eaves B-1
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	9. WELL NO. No. 18
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1980' FWL - Unit Letter C	10. FIELD AND POOL, OR WILDCAT HMTA / Seabrook Gates
14. PERMIT NO. 30-025-12015	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 7 Rws
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MTRU
2. Run scraper in 4 1/2" line to 3077'.
3. Set CIBP at 3035'. Load & circulate hole full with 97 bbl 9.5 ppq mud (9.0 ppq brine plus 25 sacks gel/100 bbl brine) Pressure test csg to 300 psi.
4. Spot 50 sx cement plug on top of CIBP. Displace w/ 13.5 bbls 9.5 ppq mud. Top of plug at 2367'.
5. POOH to 1360' & spot 35 sx cement plug. Displace w/ 6.6 bbls 9.5 ppq mud. Top of plug at 1149'. POOH.
6. Perforated 50' w/ 4 js pf. POOH.
7. Circulate 20 sx cement plug.
8. Install P&A marker.

18. I hereby certify that the foregoing is true and correct

SIGNED Don Finney J. FINNEY

TITLE Administrative Supervisor

DATE October 12, 1987

(This space for general or State office use)

APPROVAL OF
COMMISSIONS OF APPROVAL, IF ANY:

TITLE

DATE 11-9-87

*See instructions on Reverse Side

Under the Espionage Laws, it is a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Caisbad (6) ARCO (2) Amoco (2) Chevron (1) File.