

(SUBMIT IN TRIPLICATE)

Land Office Las Criiges

Lease No. 068824(d)

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

APR 25 195

PRY NOTICES AND REPORTS

NOTICE OF INTENTION TO DRILL

NOTICE OF INTENTION TO CHANGE PLANS

NOTICE OF INTENTION TO TEST WATER SHUT-OFF

NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL

NOTICE OF INTENTION TO SHOOT OR ACIDIZE

NOTICE OF INTENTION TO SHOOT OR ACIDIZE

NOTICE OF INTENTION TO PULL OR ALTER CASING

SUBSEQUENT REPORT OF ALTERING CASING

SUBSEQUENT REPORT OF REDRILLING OR REPAIR

SUBSEQUENT REPORT OF ABANDONMENT

SUBSEQUENT REPORT OF ALTERING CASING

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

			A	r11 24,	, 19.51
Well No. 2 Parker is lo	cated 1650 ft.	from $\stackrel{igwedge}{oldsymbol{lpha}}$ line a	nd 1650 ft. from	E line of se	ec23
(% Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)		
South Leonard (Field)		nty or Subdivision)		Harico State or Territory)	
The elevation of the derrick	floor above sea	level is	_ ft.		
	DET	AILS OF WO	RK		
(State names of and expected depths t	o objective sands; show ing points, and a	sizes, weights, and le all other important p	engths of proposed casings roposed work)	; indicate mudding	; jobs, cement-

April 24, 1951: Well spaided today.

Drilling Contractors - J. D. Kaynes Odessa. Texas

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Address Box 372

Rewell, New Mondes By Hausener Title Secretary Transport