

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. NMJ 538
7. Unit Agreement Name
8. Farm or Lease Name South Leonard Unit
9. Well No. 6
10. Field and Pool, or Wildcat So. Leonard Queen
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator TEXAS PACIFIC OIL COMPANY, INC.
3. Address of Operator P.O. Box 1069 - Hobbs, New Mexico
4. Location of Well UNIT LETTER H , 1980 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 23 TOWNSHIP 26-S RANGE 37-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 2988'

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull rods and tubing. Clean out. Run frac tubing and packer.
2. Frac treat with 2500 gal pad; 20,000 gal. frac fluid; 55,000# 10/20 sand in 2 stages.
3. Pull frac tubing and packer. Run tubing and swab.
4. Run pump and rods. Place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by SIGNED <u>Stedden Ward</u>	Area Superintendent TITLE <u>SUPERVISOR DISTRICT</u>	DATE <u>1-21-71</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT</u>	DATE <u>JAN 25 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JAN 22 1971

OIL CONSERVATION COMM.
HOUSTON, TEX.