

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLI
(Other instructions on
reverse side)

E*
re-

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-030174(b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

-

7. UNIT AGREEMENT NAME

-

8. FARM OR LEASE NAME

W. H. Rhodes B Fed. NCT-1

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Rhodes Yates

11. SEC., T., E., M., OR BLK. AND
SURVEY OR AREA

Sec. 27, T-26-S, R-37-E

14. PERMIT NO. Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

2988' (GR)

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Rig up. Pull rods & pump. Install BOP.
2. Clean out well to TD.
3. Fish 40' 4 1/2" OD gravel packed liner @ 3230'.
4. Clean out.
5. Set pkr. @ 3025'. Acidize open-hole section w/3000 gal NE Acid in 3-equal stages using 250# Salt between stages. Flush w/KCL water.
6. Install production equipment, test & place on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Asst. Dist. Supt.

DATE

12-21-77

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: