State of New Mexico

Form C-103

to Appropriate District Office	Energy, Minerals and Natural Resources Department		Revised 1-1-89	
DISTRICTA CONSERVATION DI P.O. Box 1980, Hoose, NM 88240ED	STRICT II O. Box 1980, Hobbe, NM. 88240ED P.O. Box 2088 STRICT II O. Drawer DD, Arlesia, NM. 882101 10 23 STRICT II O. Drawer DD, Arlesia, NM. 882101 10 23 STRICT III O. Drawer DD, Arlesia, NM. 882101 10 23 STRICT III		WELL API NO. 30 - 025 - 12	2065
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of	Lesse STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No. B 1431	
SUNDRY NOTICES AND REPORTS ON WELLS				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name RHODES YATES UNIT	
1. Type of Well:				
MET WEST OVE	OTHER Injection	Well		
2. Name of Operator			8. Well No.	
Texaco Exploration and Production Inc. 3. Address of Operator		9. Pool name or Wildcat		
P. O. Box 730 Hobbs, NM 88240		RHODES YATES SEVEN RIVERS		
4. Well Location				
Unit LetterC :	660 Feet From The NORTH	Line and	1980 Feet From	
		A7 F	> = = = = = = = = = = = = = = = = = = =	County
Section 27	Township 26-S Rai		NMPM LEA	
2996' GL				
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	GIOPNS F	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB			
OTHER: OTHER: Convert t		o Injection X		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 10-29-93 / 11-19-93 (1) MIRU. Pulled rods and pump NU BOP. Pulled tubing. (2) TIH with bit and casing scraper. Cleaned casing to 3100'. (3) Cleaned fill out of open hole to 3219'. Ran Gr-DSN-Cal log from 3216'to 2700'. (4) Perf 7" casing w/4 JSPI 3074'-3084'. Plug back open hole to 3170'. (5) Set packer @ 3020'. Frac Yates with 75K# 16/30 sand and 30K gals X-L gel. (6) Clean out hole to 3160'. Tight spot in casing @ 2566', swedged out. (7) GIH with injection tubing and packer, set @ 3038'. Circulated packer fluid. (8) Removed BOP. Flanged up tubing head. Tested casing to 500 psi. Did not hold. (9) Ran casing inspection log, located bad spot @ 2567'. (10) Request shut in injection status pending workover to repair casing. RE: WFX-644				
D-C	ue and complete to the best of my knowledge and	bellef. LE Engr Asst		DATE 01-12-94
TYPE OR PRINT NAME L.W. Johnson				TELEPHONE NO. 393-7191
(This space for State Use) DISTRICT 1 SUPERVISOR JAN 1 4 1994				