

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

Lease No. 030174-B

Unit 20

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NMOC

		X	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			
Clean out well and run logs	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

W. H. Rhodes (b)

TEXACO Inc. P. O. Box 728
Hobbs, New Mexico September 14, 1961

Well No. 5 is located 660 ft. from N/S line and 1980 ft. from E/W line of sec. 27

NW 1/4, NE 1/4, Sec. 27 T-26-S R-37-E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Rhodes Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 2992 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

To increase production we propose to do the following work:

1. Kill well with lease oil.
2. Clean out open hole section 3113' to 3265'.
3. Run tubing with seating nipple on bottom of string to total depth.
4. Run Gamma Neutron Log from surface to total depth.
5. Pull tubing from bottom into cased hole and install wellhead equipment.
6. Swab well, recover load oil, test, return well to production.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company TEXACO Inc.

Address P. O. Box 728

H. N. Wade

Hobbs, New Mexico

By H. N. Wade

Title Assistant District Superintendent