Form 3160-5 (June 1990)	DEPARTMEN	TED STATES IT OF THE INTERIOR LAND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No.							
Do not use t	his form for proposals to dr	AND REPORTS ON WELLS III or to deepen or reentry to a of R PERMIT—" for such proposal		LC- 030174 b 6. If Indian, Allottee or Tribe Name						
	SUBMIT	IN TRIPLICATE		7. If Unit or CA, Agreement Designation						
1. Type of Well X Well				W. H. RHODES B FED NCT-1						
2. Name of Operato	r Well Other			8. Well Name and No. NCT-1 #6						
	ploration and Production I	nc.		9. API Well No.						
3. Address and Tele PO Box 7	phone No. 130, Hobbs, NM 88240	E	05 207 0409	30-025-12069						
	(Footage, Sec., T., R., M., or Survey D		05-397-0428	10. Field and Pool, or Exploratory Area Rhodes Yates 7-R						
	980 FSL. 660 FEL	····· • • • • • • • • • • • • • • • • •		11. County or Parish, State						
•	′, T−26−S, R−37−E									
				Lea County, NM						
·		s) TO INDICATE NATURE OF		RT, OR OTHER DATA						
	E OF SUBMISSION		TYPE OF ACTION	<u>v</u>						
۱ لکا	Notice of Intent	Abandonment		Change of Plans						
\Box	Subsequent Report	Recompletion								
	abacularin Report	Casing Repair		Non-Routine Fracturing Water Shut-Off						
	Final Abandonment Notice	Altering Casing		Conversion to Injection						
		Other		_ Dispose Water						
				(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)						
 MIRU. P TIH with Run CBU 240 sc das Run CBU 240 sc das GIH with GIH with GIH with GIH with Frac open flow back Drill cut I Run prod 	the locations and measured and true vertice will rods and pump. NU BOP. Pull tubing, F bit and 5-1/2" casing scraper. Clean casing a , and find TOC. Shoot squeeze perfs and PC s 'C. POH. GIH with bit and dnil out ceme wireline, perf 3078'-3152' based on GNT @ packer and set at 3000'. Acidize perfs with 3 bulklog bailer or side jet and reverse unit an hole with 20/40 frac sand to top of zone 7 an	al depths for all markers and zones pertinent to "ick up work string nd analyze scale. Tag fill. WH Set RBP above shoe and cap with sand. GilH w art plug. Test casing squeeze. 4 SPF. 000 gals 15% NEFE in three stages with rock salt nd clean full out of open hole. POH. Acidize open nd cap with 20 of resin coated sand and a 10 hydr 1000 gal X-L gel and 71,400# 20/40 Ottawa includ ing. POH. e any fill on top of plug.	o this work.)* with packer and test casing. Est t blocks. Swab or flow back los hole with 1000 gals 15% NER romite plug. WOC and tag pl	E if necessary.						
Signed 1	hat the foregoing is true and correct R. McNaught ederal or State office use) proval, if any:	ton <u>Title</u> Production Engine	eer So.	Date 12/8/92						

Tide 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

PO-108 Proposed Injection Conversion (8/92)	OPERATOR: Texaco Exploration & Production Inc. Lease: Rhodes B Fed NCT-1 #6	Bec./Twn/Rng: Unit I, Sec 27, T-26-S, R-37-E	Lea County, New Mexico	<u>TABULAR DATA</u> Surface Casing: Set at 1212'	Size <u>8-5/8, 32</u> # Cemented with <u>200</u> sx.	TOC 40 'determined by calculated	Hole Size <u>11"</u> Comp. Date <u>8-11-44</u>	Intermediate casing: Set at	Size <u>NONE</u> Cemented with <u>sx</u> .	TOC determined by	Hole Size (Perfs to be added: 3048'-3150')	Production Casing: Set at 3162'	Size <u>5-1/2", 14</u> # Cemented with <u>300</u> sx.	TOC <u>1660</u> ' determined by <u>calculated</u>	Hole Size 7-1/2", 4-3/4" open hole	Injection Interval:	<u>3048</u> ' to <u>3300</u> ' through: OH, Perforations	Tubing: 2-3/8", 4.7#, J-55, IPC 2000# WP	
		FOOTAGE LOCATION: 1980 FSL X 660 FEL	Former Texaco Rhodes 'B' #6	SCHEMATIC				TOC & 40. / CATC.				T/ added Yates Portan Fortan F	J162 2-1/2", 14#, 300 SX, TOC 0 1660, calc.	3300' () OH TD		•	2922' 2922'	STANTY	

•