

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY U. S. G.SUBMIT IN _____ DATE _____
(Other Instru-
verse side)Form Approved
Budget Bureau No. 42-E1421
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen a well or to change back to a different reservoir.
Use "APPLICATION FOR PERMIT TO DRILL" for such proposals.)

LC-030168 2

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR

NMFU

8. FARM OR LEASE NAME

3. ADDRESS OF OPERATOR

EAKES A

9. WELL NO.

Box 460, Hobbs, New Mexico 88240

14

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

10. FIELD AND POOL, OR WILDCAT

Dearborn 3 water 7 B

660' FNL & 660' FWL of Sec. 30, T-26S,

11. SEC., T., R., M. OR BLS. AND
SURVEY OR AREA

R-37E, in Lea County, N. Mex.

Sec. 30, T-26S, R-37E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

12. COUNTY OR PARISH

13. STATE

2927 GR

Lea

N. MEX.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Perforate Additional Pay

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is proposed to perforate additional pay by the following procedures.

Perforate from 3146' to 3175' with one $\frac{3}{8}$ " JSPF. Set a RBP at 3182'. Treat new pipe with 2,000 gals 15% LSTNE acid. Overflush with 50 barrels of produced water. Place well on test. If test is satisfactory, place well on production. If test is not satisfactory, pull RBP and place well on production

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert H. Smith

TITLE

Administrative Section Chief

DATE

8-20-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE

AUG 21 1969

USGS - 5

2.60

Per am Hobbs &
M. Pick-Pick

*See Instructions on Reverse Side

Chw. mid 2

J L GORDON
ACTING DISTRICT ENGINEER