

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN (Other Instr. on reverse side) PLICATE

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. LC-030168B
2. NAME OF OPERATOR Conoco Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 1980' FEL - Unit Letter J		8. FARM OR LEASE NAME Eaves B-1
14. PERMIT NO. 30-025-12084		9. WELL NO. No. 2
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		10. FIELD AND POOL, OR WILDCAT MMU/Scarborough Gates
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 7 RURS
		12. COUNTY OR PARISH Lea
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRR.
2. Set CIBP at 2750'. Load & circulate hole full w/ 24 bbls 9.5 ppq mud (9.0 ppq brine plus 25 sxs-gel/100 bbls brine). Pressure test to 300 psi.
3. Perforate at 2740' w/ 4 spf. POOH.
4. Pump 170 sx cement plug down 3 1/2" lined & up lined-csg annulus. Displace w/ 10.9 bbls 9.5 ppq mud, top of plug at 1250'.
5. Perforate through both csg strings at 300' w/ 4 spf. POOH.
6. Pump 150 sx cement plug down 3 1/2" lined.
7. If cement returns are not received up both sets of pipe, coil Hgs should be used to spot a 50' plug to surface.
8. Install P & A marker

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Administrative Supervisor

TITLE Administrative Supervisor

DATE October 12, 1987

This space for Federal or State office use

APPROVAL OF
COMMISSIONERS OF APPROVAL, IF ANY:

TITLE

DATE 11-9-87

*See instructions on Reverse Side

Title 18 USC, Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlbad(6) ARCO(2) Amoco(2) Chevron(1) File

RECEIVED
NOV 12 1987
CCO
HOBBS OFFICE