

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Javes B-1
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	9. WELL NO. No. 6
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1980' FEA - Unit Letter B	10. FIELD AND POOL, OR WILDCAT 77777 / Scarborough York 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA 7 RRS 31-26S-37E
14. PERMIT NO. 30-025-12088	15. ELEVATIONS (Show whether DF, RT, GR, etc.)
12. COUNTY OR PARISH Dea	
13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRR.
2. Run Scraper.
3. Set CIBP at 2900'. Load & circulate hole full w/ 111 bbl 9.5 ppq mud (9.0 ppq brine plus 25 sxs gel / 100 bbls brine). Pressure test casing to 300 psi.
4. Spot 40 sxs cement plug on top of CIBP. Displace w/ 15.4 bbls of 9.5 ppq mud. Top of plug at 2668'.
5. POOH to 1305' & spot 20 sxs cement plug. Displace w/ 6.8 bbls 9.5 ppq mud. Top of plug at 1189'.
6. POOH to 62' & circulate a 20 sxs surface cement plug.
7. Install P & A marker.

18. I hereby certify that the foregoing is true and correct

SIGNED DI FINNEY

TITLE Administrative Supervisor

DATE October 12, 1987

This space for agency or State office use

APPROVAL OF
COMMISSIONS OF APPROVAL, IF ANY:

TITLE

DATE 11-5-87

*See instructions on Reverse Side

Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) ARCO(2) Amoco(2) Chevron(1) File