W. Res MBOLOHC EME OCA Lobbs

	DEPARTMEI	TED STATES NT OF THE INTERIOR	FORM APPROVED Budget Bureau No. 1004-0135	
	BUREAU OF	LAND MANAGEMENT	5. Lease Designation and Serial No.	
	SUNDRY NOTICES	S AND REPORTS ON WELLS	LC030168B 6. If Indian, Allottee or Tribe Name	
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals			o. It stidially stillocted of Thise statute	
SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation	
1. Type of Well Oil Well	Gas		8. Well Name and No.	
2. Name of Op	Well Other		EAVES B #1	
SOUTHWEST ROYALTIES, INC.			9. API Well No.	
3. Address and Telephone No. P.O. BOX 11390 MIDLAND, TX 79702 915 1800-433-7945			30 025 12083 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SEC. 30 T26S R37E 1980 FNL & 1980 FeL			SCARBOROUGH YATES 7 RVRS	
SEC, 30 T26S R37E 1980 FNL & 1980 FeL			11. County or Parish, State	
			LEA COUNTY, NM	
12. (CHECK APPROPRIATE BOX(s	s) TO INDICATE NATURE OF NOTICE, REPORT, O	R OTHER DATA	
	TYPE OF SUBMISSION	TYPE OF ACTION	OF ACTION	
	Notice of Intent	Abandonment	Change of Plans	
		Recompletion	New Construction	
	Subsequent Report	Plugging Back	Non-Routine Fracturing	
	Final Abandonment Notice	Casing Repair Attering Casing	☐ Water Shut-Off ☐ Conversion to Injection	
		Other REQUEST TA STATUS	Dispose Water (Note: Report results of multiple completion on Well	
13. Describe P	roposed or Completed Operations (Clearly s	state all pertinet details, and give pertinent dates, including estimated date	Completion or Recompletion Report and Log form.) Of starting any proposed work. If well is	
REQUEST JUSTIFICA 6-20-97	ordilled, give subsurface locations and mean TA STATUS ON THE ABOVE WE ATION FOR NOT PLUGGING WEL SET CIBP @ 2844'. RAN CIT.	sured and true vertical depths for all markders and zones pertinent to this v	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)*	
REQUEST JUSTIFICA 6-20-97	ordilled, give subsurface locations and mean TA STATUS ON THE ABOVE WE ATION FOR NOT PLUGGING WEL SET CIBP @ 2844'. RAN CIT.	ELL. LL: The wellbore has workover potential (future perfs 2880-ESTING IS COMPLETED ON EAVES B-20.	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* 2910' OA).	
directionally REQUEST JUSTIFIC, 6-20-97 REQUEST	ordilled, give subsurface locations and mean TA STATUS ON THE ABOVE WE ATION FOR NOT PLUGGING WEL SET CIBP @ 2844'. RAN CIT.	ELL. L: The wellbore has workover potential (future perfs 2880- ESTING IS COMPLETED ON EAVES B-20. Approved For 12 fronth Period Ending 60201	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* -2910' OA).	
directionally REQUEST JUSTIFICA 6-20-97 REQUEST	TA STATUS ON THE ABOVE WEATION FOR NOT PLUGGING WELLSET CIBP @ 2844'. RAN CIT. TA CONTINUE UNTIL AFTER TE	ELL. L: The wellbore has workover potential (future perfs 2880- ESTING IS COMPLETED ON EAVES B-20. Approved For 12 Month Period Ending 600 2001 Title ENGINEER	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* -2910' OA).	

RECEIVED
FEB 01 01

