

Bert Fields, Jr

LOCATION OF WELL SERVICED

A.F.E. NO. AUTHORIZED BY

DESCRIPTION OF SERVICE ORDERED
Plug & abandon

DATE 11-16-87	JOB OR ORDER NUMBER
LEASE State O	WELL NO.
CONTRACTOR	


Mayo Marris Casing Pulling

JOB STARTED 11-16-87	JOB COMPLETED 11-16-87
-------------------------	---------------------------

TD _____, PBD _____, PERFORATIONS _____

REASON FOR PULLING WELL: ☐ Rods parted, ☐ Pump Repair, ☐ Tbg. Leak, ☐ Other Plug & abandon

CONDITIONS FOUND UPON PULLING: RODS: ☐ Box break, ☐ Body break, ☐ Upper pin, ☐ Lower pin, ☐ OK
PUMP: ☐ Plunger worn, ☐ Balls & Seats worn, ☐ Barrel worn, ☐ Other, ☐ OK
TBG: Leak @ _____, ☐ OK
INDICATIONS OF CORROSION: ☐ Pump, ☐ Rods, ☐ Tbg, ☐ Other, ☐ None
OTHER:



200' to top
40 sacks m top

1050'
1250'
Set 40 sacks
for Rustler
water

2640'
Set plug
in hole with cement
on top & bottom.
Top @ 2640'

TUBING	SIZE 2 3/8" 10V	TYPE	GRADE H 40
	NO. JOINTS 97	DEPTH	S.N. DEPTH
WAS TUBING RUN OPEN ENDED ☐ YES ☒ NO			
PACKER	SIZE	MAKE	SETTING DEPTH
	TYPE left in hole		
RODS	SIZE	NO.	SIZE
	SIZE	none	NO.
SUB SURFACE PUMP		MAKE	SIZE
PUMPING UNIT		MAKE	SIZE
PRIME MOVER		MAKE	SIZE/H.P.
SPECIAL EQUIPMENT Debit Valve & Choke			
BRIEF RESUME ON PROCEDURE Rigged up. Unpacked packer and spatted mud. Put 40 sacks cement from 2880' to 2640'. Spatted 4 hrs and tagged at 2640'. Put 40 sacks cement from 1250' - 1050'. Tagged. Set top plug in well. 11-17-87 Put up designated marker (Lombstone)			

EQUIPMENT CHANGED

Well File
STATE O

AFTER	CLEANED OUT	FROM	TO
AFTER		OIL	
IL	WATER	WATER	REMARKS
CASING PRESSURE		TUBING PRESSURE	TITLE
TITLE		SIGNED BY Lb	