## N

## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fo, New Mexico

## **WELL RECORD**

Mail to Oil Conservation Commission, Santa Fe, New Mexico, or its proper agent not more than twenty days after completion of well. Follow instructions in the Rules and Regulations of the Commission. Indicate questionable data

LQCAT		ACRES CORRECTLY		by follo	wing it wi	P. O.				, New Hea	cico
	y B. Wi	Company or	<del></del>	3	· · · · · · · · · · · · · · · · · · ·	ME		3/	Address	268	<del></del>
	Lease	*****	Well No:		1	n	of	Sec.	*	, Т	
R. 37E	_	, N. M. P. I	M., Rhoe	166	660	_Field,			Les	Sec. 34	Count
AA C11 19***			of the North			teet w		ie East li			•
			ase is No.			_Assignme					
-		owner is the perm	Mary		Wille	<u>, (, , , , , , , , , , , , , , , , , , </u>	•	Address.	Catle	bad, New	Mexico
II Govern The Lesse			Oil Com	any		· · · · · · · · · · · · · · · · · · ·	<del></del> ,	Address	Houst	on 2, Tex	(A.S
	ommence	Marc	oh 24		1945	Drilling				1 15	19 45
_			lsen-Blou	nt Co	rp.	,		711a7 m k	lone,	City, Ok	ia.
Elevation	above sea	level at to	op of casing	298	19	feet.					
The infor	mation gi	ve <b>n</b> is to be	kept confide	ntial u	ntil					19	•
		205	21		IL SAND	s or zon					
No. 1, fro	1(1	3195		337							
			to								
<b>No. 3, fr</b> o	m		to							to	
						WATER S					
			inflow and								
			,								
110. 1, 11	V 4 1 2					RECORI					
							====				
SIZE	WEIGH PER FO		TADS INCH MAE	E A	MOUNT	KIND OF SHOE	CUT &	FILLED M	FROM	ERFORATED	
5/8 OD	30	8-V	J&L	12	233	HOWCO			None		Surfa
1/2 OD	17	8 R	nd. Young	e de cons	1 3155	HOWCO		****	None		011 3
L/R 00	47	0 20	toures		. ,43,						
						<del></del>	<u> </u>				
			MU	DDIN	G AND C	ementin	G RECO	RD			
	Gran OB		NO SAO	ar a			<del> </del>		. 1		<del>- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1</del>
SIZE OF	SIZE OF CASING	WHERE SE	1	ENT	METH	OD USED		IUD GRAY	/ITY	AMOUNT	OF MUD USE
n	8-5/8	1233	350		Berry.	our con		70		****	
7-3/8	<b>4-1/2</b>	3155	325		Hallit	mrton		10		40	
, ,,,	7 -/-	<b>3</b> -77					+				
					LUGS AN	D ADAPT	ERS		<del></del>		
Heaving	plugM	aterial			_Length_				_Depth	Set	
			RECORD OF	в вно	OTING	OR CHEM	ICAL 7	TREATM	ENT		
	+							2224			<del></del>
SIZE		L USED	CHEMICAL U	or sed	QUANT		ATE		H SHOT REATED	1	CLEANED OF
3-1/2	4 -	20Qte	Nitro		80 Qt	4/4	1/45	2200	<u>ر</u> ں،	22. 22.	· · · · · · · · · · · · · · · · · · ·
	<u> </u>			Well	made '	369 bbls	in 2	4 hre	before	shot. a	fter shoo
Results	of shootin	g or chemi	cal treatment is. oil w	rith (	GOR 79	4:1					
							annor.	A TOTAL OF	<u> </u>		
T# 4-211 -	at	han anasial	•			rem AND				to sheet and	d attach here
II uriii-s	tem or ot	ner speciai	tests of devi	acion s			Suparic	report o	n scpara	ic snoce and	i actaon nore
			0		3 <b>3</b> :	LS USED 37		<b>6</b>		foot to	f
		used from		feet							
Cable to	ous were	used iron		1961			et, and	110111			
_		May 1	L		PRO 45 19	DUCTION					
_	roducing_				·		η <b>ρ ρ</b> 111222	of which	100	Ø_ wee e	0
amulaior	O O	the first 24	ater; and	)	or. su	Darreis	Orovity	Re	35.5	a 60 Deg.	il;
		per 24 hou			70 B				00 cu. fi	. of gas	
-		s. per sq. in	1060 (4	ifter	shut	in for	14 hrs	3)****			
2000m F-					EMI	PLOYEES					
W.	P. Mor	ris						. C. Hi			D-1
A.	V. Nic	hols			•	ler ler					, Dri
				n 3 - 1							, Dri
						ORD ON					
								ete and	correct	record of the	he well and
work do	one on it :	so far as ca	in be determi	ined fr	om avail	adie record	18.				
Suhannii	ed and e	vorn to bef	ore me this_	3	rd	Ho	bbs, l	lew Mex	ರಣ	May 3, 3	1945
Subscrit	ou and St		ore me this		45	<u> </u>	Plac	e /			Date
day of	<b>→</b>				. 19	Nam		Letrici	Post		Mary 1
	XX	1,100	llau/			Posit			<del></del>		
<del></del>	<u> </u>	1	Notary P	ublic		Renr	esenting		hio O	il Compan	n <b>y</b>

Representing\_

My Commission expires 17 COMMISSION EXPIRES AUG. 19, 1947

Representing

Company or Operator

P. O. Box 1607, Hobbs, New Mexico

		F	ORMATION RECORD	
0 110 1020 1115 1153 1468 1592 1673 1850 2080 2288 2505 2692 2860 2870 2990 3000 3027 3102 3195 3280 3321 3336	110 1020 1115 1153 1468 1592 1673 1850 2080 2288 2505 2692 2860 2870 2990 3000 3027 3102 3195 3280 3321 3336 3337	THICKNESS IN FEET  110 910 95 38 315 124 81 177 230 208 217 187 168 10 120 10 27 75 93 85 41 15 1	Clay Red Rock Anhydrite & Shells. Red Rock. Anhydrite. Salt & Anhydrite. Salt & Anhydrite. Salt & Anhydrite - Shells. Anhydrite & Salt. Anhydrite & Salt. Anhydrite & Salt. Anhydrite - Sandy. Lime. Yates Sand. (No show of gas Lime. Broken. Lime, Gypsum Lime. Sand W/Gas & Oil staining. Sand, staurated. Sand, saturated, very soft. Hard White Lime.	